



Product Change Notification

104847 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANdesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 104847 - 00
Change Title: SR1400, PCN 104847-00, FYI, Class2; Low Profile PCI-X Riser Card Change
Date of Publication: February 17, 2005

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Feb 18, 2005
---	--------------

Description of Change to the Customer:

The current low profile PCI-X riser card used in the server chassis SR1400 has the potential of interference with a capacitor on the Intel server board SE7520JR2. This issue has been correct by removing the material on the riser card in the interference area.

Customer Impact of Change and Recommended Action:

Intel anticipates no customer impact for this change. Evaluate when available.

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SR1400	857036	857036	C51952-004	C51952-005	C53356-401	C53356-501
SR1400NA	857140	857140	C51952-004	C51952-005	C53356-401	C53356-501
SR1400SYS	865571	865571	C50219-005	C50219-006	C53356-401	C53356-501
SR1400SYSNA	865595	865595	C50219-005	C50219-006	C53356-401	C53356-501

Component Product Table

Pre-Conversion Product Code	Pre-Conversion Spec/ROM	Pre-Conversion MM#	Post-Conversion Product Code	Post-Conversion Spec/ROM	Post-Conversion MM#
ADWLPRISER		861837			861837

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision:

February 17, 2005

Revision Number:

00

Reason:

Originally Published PCN