



Product Change Notification

104464 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2004. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.



Product Change Notification

Change Notification #: 104464 - 00
Change Title: SE7501HG2, BSE7501HG2, PCN 104464-00, FYI, Class 1: Update BIOS, update Resource CD with the latest version of System Setup Utility, replace two capacitors
Date of Publication: October 18, 2004

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:

Product Material
Documentation
Software
Order Code

Forecasted Key Milestones:

Date of First Availability of Post-Conversion Material:	Nov 05, 2004
--	--------------

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

BIOS on the board will be updated to P13-0051.

Resource CD will be updated with the latest version of System Setup Utility.

Two capacitors on base board at location C8V8 and C8V7 will be changed from 18pf value to 10pf value of the same type capacitors.

Customer Impact of Change and Recommended Action:

Orders for BSE7501HG2 SKU will need to be submitted using the new MM#.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BSE7501HG2	857555	858347	C11452-307	C11452-308	A95718-307	A95718-308

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
SE7501HG2	850354	850354	C11477-005	C11477-006	A95718-307	A95718-308

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
October 18, 2004	00	Originally Published PCN