



Product Change Notification

103857 - 02

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2004. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash, Trillium is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 103857 - 02
Change Title: SR2300, PCN 103857-02, FYI, Class 2;
Module FRU Change and AC Inlet Label
Move for the 500W Power Supply
Date of Publication: February 10, 2004

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Software

Forecasted Key Milestones:

Date of First Availability of Post-Conversion Material:	Feb 20, 2004
--	--------------

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

- 1) Updating FRU information on the 500W power supply to ensure compliance with the IPMI specification.
- 2) Moving the AC inlet rating label to prevent interference with chassis grounding fingers when installing.

Customer Impact of Change and Recommended Action:

- 1) Updating FRU information on the 500W power supply cage and the 500W power supply module to ensure compliance with the IPMI specification - Customer needs to be aware of the change; no impact to customer expected.
- 2) Moving the AC inlet rating label to prevent interference with chassis grounding fingers when installing - Customer needs to be aware of the change; no impact to customer expected.

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
-----------------------	----------------	-----------------	---------------	----------------	------------------------	-------------------------

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
AXX2PSMODL500	847521	847521	A81338-003	A81338-004	A76009-005	A76009-006
KSW	854056	854056	A81074-016	A81074-017	A76009-005	A76009-006
SE7501WV2SKU02	855630	855630	C22264-013	C22264-014	A76009-005	A76009-006
SWV2USKU07	853492	853492	C32002-008	C32002-009	A76009-005	A76009-006

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

January 22, 2004

00

Originally Published PCN

February 4, 2004

01

Due to factory inventory this change is being split into two separate PCN's

February 10, 2004

02

Correction to TA number