



Product Change Notification

106663 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106663-01
Change Title: SE7230NH1, SE7230NH1LX, BNHBB and BNHBBLX, PCN 106663-01, Product Material, Class 1, Change to BIOS Release NH1179, Replace 2x4 CPU Power connector and updated ten pack carton., Reason for Revision: Adding Part number for CPU 2 x 4 connector
Date of Publication: August 08, 2006

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 28, 2006
---	--------------

Description of Change to the Customer:

Reason for Revision: Adding Part number for CPU 2 x 4 connector

The server board BIOS will be changing to production release NH1179. See the BIOS release notes for a list of changes, available at support.intel.com. Change the 2 x 4 CPU power connector (J1B2) from A91854 to A91854-015. The new power connector has a longer tab allowing 2 x 2 power leads to be connected the server board. The ten pack carton (C61552-001) is replaced with D54268-001 to accomodate better pallet desity. The boards will be protected by corrugated carton material on the sides vs the previous air space protection.

Customer Impact of Change and Recommended Action:

Eval when received

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BNHBB	872468	872468	D18675-402	D18675-403	D18676-402	D18676-403
BNHBBLX	872467	872467	D13543-402	D13543-403	D13542-402	D13542-403
SE7230NH1	872389	872389	D18675-402	D18675-403	D18676-402	D18676-403
SE7230NH1LX	872388	872388	D13543-402	D13543-403	D13542-402	D13542-403

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

August 7, 2006

00

Originally Published PCN

August 8, 2006

01

Adding Part number for CPU 2 x 4
connector