



# Product Change Notification

## 104219 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geography location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

Asia Pacific Contact: [apacgccb@intel.com](mailto:apacgccb@intel.com)

Europe Email: [eccb@intel.com](mailto:eccb@intel.com)

Japan Email: [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2004. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 104219 - 00  
**Change Title:** DI0408LSA, DI0408LSAJP, DI0408LSACN, PCN 104219-00, PD, Product Discontinuance due to End Of Life of Constituent Board Components and Availability of Improved or Cost Reduced Products  
**Date of Publication:** July 15, 2004

**Type of Change Notification:**  
PD - (Product Discontinuance)

**Key Characteristics of the Change:**  
Product Discontinuance

## Forecasted Key Milestones:

<b>Product Discontinuance Program Support Begins:</b>	Jul 15, 2004
<b>Last Product Discontinuance Order Date:</b>	Jan 01, 2005
<b>Last Product Discontinuance Shipment Date:</b>	Apr 02, 2005

## Description of Change to the Customer:

Due to End of Life of constituent board components and availability of improved or cost reduced products some DI0408LSA products are being discontinued. Specific Product Codes being retired are listed below.

## Customer Impact of Change and Recommended Action:

Please determine your remaining demand for the affected product and place orders in accordance with the key milestones listed. Last Product Return Date is October 2, 2004. Orders are non-cancelable and non-returnable after October 2, 2004.

Contact your sales representative for additional migration information and/or any issues you may have with this Product Discontinuance Plan.

### Migration Plan

The following DI0408LSAR2 products are recommended as migration products.

<u>Product Names</u>	<u>MM</u>	<u>Migration Product</u>	<u>MM</u>
DI0408LSA	838536	DI0408LSAR2	858167
DI0408LSA	840808	DI0408LSAR2	858167
DI0408LSA	841131	DI0408LSAR2	858167
DI0408LSA	849229	DI0408LSAR2	858167
DI0408LSA	850975	DI0408LSAR2	858167
DI0408LSA	853810	DI0408LSAR2	858167
DI0408LSA	853831	DI0408LSAR2	858167
DIO408LSAJP	843227	DI0408LSAR2JP	858168
DIO408LSAJP	849230	DI0408LSAR2JP	858168
DIO408LSAJP	850973	DI0408LSAR2JP	858168
DIO408LSAJP	853835	DI0408LSAR2JP	858168
DIO408LSAJP	853836	DI0408LSAR2JP	858168
DI0408LSACN	846339	DI0408LSAR2	858167
DI0408LSACN	849231	DI0408LSAR2	858167
DI0408LSACN	850974	DI0408LSAR2	858167
DI0408LSACN	853837	DI0408LSAR2	858167
DI0408LSACN	853838	DI0408LSAR2	858167

### **Products Affected / Intel Ordering Codes:**

#### **Board Products Table**

<b>Affected Product Code</b>	<b>Affected MM#</b>
DI0408LSA	838536
DI0408LSA	840808
DI0408LSA	841131
DI0408LSA	849229
DI0408LSA	850975
DI0408LSA	853810
<b>DI0408LSA</b>	<b>853831*</b>
DI0408LSAJP	843227
DI0408LSAJP	849230
DI0408LSAJP	850973
DI0408LSAJP	853835
<b>DI0408LSAJP</b>	<b>853836*</b>
DI0408LSACN	846339
DI0408LSACN	849231
DI0408LSACN	850974
DI0408LSACN	853837
<b>DI0408LSACN</b>	<b>853838*</b>

**Active Products** are denoted by \*

### **Reference Documents / Attachments:**

**Document:**

**Location #:**

### **PCN Revision History:**

**Date of Revision:**

**Revision Number:**

**Reason:**

July 15, 2004

00

Originally Published PCN