



# Product Change Notification

## 107314 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 107314 - 01  
**Change Title:** S5000PAL based systems, Class 1, PCN 107314-01, Product Design, Updating Installed System Software, Reason for Revision: Adjusting dates and adding TA numbers  
**Date of Publication:** April 05, 2007

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

|   |              |
|---|--------------|
| <b>Date Customer Must be Ready to Receive Post-Conversion Material:</b> | Apr 27, 2007 |
|---|--------------|

## Description of Change to the Customer:

### Reason for Revision: Adjusting dates and adding TA numbers

Intel is implementing the baseboard changes from PCN #107313 into the associated systems. The changes are:

Change 1)

The system software programmed at the factory is being updated.

BIOS - From R66 to R74

BMC - From R55 to R58

FRUSDR - From R38 to R40

The system software updates, including release notes for each, will be available for download from Intel's secure website IBL, and from Intel's support website:

<http://support.intel.com/support/motherboards/server/S5000PAL/>

Change 2)

Intel is also removing an unused flash device from the board. The device is currently located at U3E1. This change will have no functional impact to the board.

These changes will implement concurrently with the changes outlined in PCNs #107372, #107453, and #107312

## Customer Impact of Change and Recommended Action:

Server Boards and Platforms, Product Design, Customers may want to perform re-qualification, re-test, re-certification or standard validation testing for this change

### Products Affected / Intel Ordering Codes:

| Pre Change Product Code | Pre Change MM# | Pre Change TA | Pre Change PBA | Post Change MM# | Post Change TA | Post Change PBA |
|-------------------------|----------------|---------------|----------------|-----------------|----------------|-----------------|
| SR1550ALNA              | 885486         | D50324-009    | D13607-804     | 885486          | D50324-010     | D13607-805      |
| SR1550ALSASNA           | 885487         | D50323-010    | D13607-804     | 885487          | D50323-011     | D13607-805      |
| SR1500ALSASNA           | 885483         | D47497-011    | D13607-804     | 885483          | D47497-012     | D13607-805      |
| SR1500ALNA              | 885482         | D47500-010    | D13607-804     | 885482          | D47500-011     | D13607-805      |
| SR2500ALBRPNA           | 885498         | D43693-013    | D13607-804     | 885498          | D43693-014     | D13607-805      |
| SR2500ALLXNA            | 885499         | D43690-015    | D13607-804     | 885499          | D43690-016     | D13607-805      |
| SR2500ALOEMNA           | 885500         | D51593-016    | D13607-804     | 885500          | D51593-017     | D13607-805      |
| SR1500AL                | 885480         | D47500-010    | D13607-804     | 885480          | D47500-011     | D13607-805      |
| SR1500ALSAS             | 885481         | D47497-011    | D13607-804     | 885481          | D47497-012     | D13607-805      |
| SR1550AL                | 885484         | D50324-009    | D13607-804     | 885484          | D50324-010     | D13607-805      |
| SR1550ALSAS             | 885485         | D50323-010    | D13607-804     | 885485          | D50323-011     | D13607-805      |
| SR2500ALBRP             | 885488         | D43693-013    | D13607-804     | 885488          | D43693-014     | D13607-805      |
| SR2500ALLX              | 885489         | D43690-015    | D13607-804     | 885489          | D43690-016     | D13607-805      |
| SR2500ALOEM             | 885496         | D51593-016    | D13607-804     | 885496          | D51593-017     | D13607-805      |

### Reference Documents / Attachments:

Document:

Location #:

### PCN Revision History:

Date of Revision:

Revision Number:

Reason:

February 21, 2007

00

Originally Published PCN

April 5, 2007

01

Adjusting dates and adding TA numbers