



Product Change Notification

107658 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107658 - 00

**Change Title: D945GTPLKR, PCN 107658-00,
Product Material, Remove ATMEL
SPI from BOM**

Date of Publication: June 18, 2007

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jun 22, 2007
---	--------------

Description of Change to the Customer:

ATMEL SPI will be removed from BOM to ensure iAMT compatibility

Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. CDPG is not recommending additional qualification of these changes on platforms received from Intel. These board changes are not expected to cause a change to the Microsoft* Windows* operating system's software driver stack. No expected OS image change.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Pre Change PBA	Post Change AA	Post Change PBA
LAD945GTPLKR 868931	868931	97837-307	C97838-307	C97837-308	C97838-308
BLKD945GTPLKR 869549	869549	97837-307	C97838-307	C97837-308	C97838-308
BOXD945GTPLKR 869550	869550	97837-307	C97838-307	C97837-308	C97838-308
LAD945GTPLK2 876656	876656	D36047-307	D36048-307	D36047-308	D36048-308

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

June 18, 2007

Revision Number:

00

Reason:

Originally Published PCN