



Product Change Notification

106985 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106985 - 01
Change Title: S5000VCL,PCN 106985-01, Product Material, Updating BIOS to Production 68, BMC 56, FRU/SDR 14 and Board Changes, Reason for Revision: Updated information
Date of Publication: December 13, 2006

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Dec 29, 2006
---	--------------

Description of Change to the Customer:

Reason for Revision: Updated information

The Intel(R) Server Board S5000VCL software is being updated to BIOS production 70, BMC 56 and FRU/SDR 14. The S5000VCL board video stepping change to replace EOL part, remove temp sensor at location U1A4. Adding diagnostic Post LED's.

Resource CD changes: Intel Deployment Assistant CD updating to version 1.2, Intel Server Management CD is updating to version 1.5. (Boxboard product only)

Customer Impact of Change and Recommended Action:

Intel anticipates no customer impact for this change. Evaluate when available.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
S5000VCL	883249	D59237-001	D41874-601	883249	D59237-002	D41874-602
S5000VCLSASBB	884049	D69372-601	D24481-601	887859	D69372-602	D24481-602

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

November 10, 2006

December 13, 2006

Revision Number:

00

01

Reason:

Originally Published PCN

Updated information