



Product Change Notification

109157 - 03

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2010. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109157 - 03
Change Title: Intel® RAID Controller SRCSASRB, PCN 109157-03, Product Design, Revision to Firmware on Controller, Reason for Revision: Incorrect firmware programmed on controller
Date of Publication: February 26, 2010

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 15, 2010
---	--------------

Description of Change to the Customer:

Reason for Revision: Incorrect firmware programmed on controller

Following changes are being communicated for Intel® RAID Controller SRCSASRB:

The conveyed firmware version 1.40.82-0732 to be programmed on the controller was not adhered to. Instead, firmware version 1.40.92-0746 was programmed on the controller.

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customer.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change Product Code	Post Change MM#	Post Change TA	Post Change PBA
SRCSASRB 892598	892598	E15152-003	D92806-154	SRCSASRB	892598	E15152-004	D92806-155

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision: August 13, 2009 **Revision Number:** 00 **Reason:** Originally Published PCN

November 1, 2009	01	Update Firmware Version and Printed Circuit Board
December 18, 2009	02	Remove Resource CD update from this ECO
February 26, 2010	03	Incorrect firmware programmed on controller