



Product Change Notification

106909 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106909 - 00
Change Title: SR6850HW4M, PCN 106909-00, Product Design, Class 2:FHW6USCSIBP-SCSI blackplane PLD update
Date of Publication: November 03, 2006

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

| | |
|---|--------------|
| Date Customer Must be Ready to Receive Post-Conversion Material: | Nov 17, 2006 |
|---|--------------|

Description of Change to the Customer:

Update SCSI backplane PLD code to allow Hot Swap Controller firmware update to work correctly with new GEM 359 controller.

SR6850HW4M (SHW6URM)

Change the MM# from 877219 to 879452

Change top assembly part number from D35289-002 to D35289-003

Change the SCSI backplane part number from C61492-450 to C61492-451

FHW6USCSIBP

MM 881408

Change top assembly part number from C98778-003 to C98778-004

Change the SCSI backplane part number from C61492-450 to C61492-451

Customer Impact of Change and Recommended Action:

No significant impact on product/process/material performance, appearance, quality, reliability, interchangeability, functionality or customer handling and manufacturability

Products Affected / Intel Ordering Codes:

| Pre Change Product Code | Pre Change MM# | Pre Change TA | Pre Change PBA | Post Change MM# | Post Change TA | Post Change PBA |
|-------------------------|----------------|---------------|----------------|-----------------|----------------|-----------------|
| FHW6USCSIBP 881408 | 881408 | C98778-003 | C61492-450 | N/A | C98778-004 | C61492-451 |
| SHW6URM 877219 | 877219 | D35289-002 | N/A | 879452 | D35289-003 | N/A |

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

November 3, 2006

Revision Number:

00

Reason:

Originally Published PCN