



Product Change Notification

107421 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107421 - 00
Change Title: DG965WH, PCN 107421-00, Product Design, Adding alternate component to support manufacturability, updated BIOS and improved board power design
Date of Publication: March 28, 2007

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

| | |
|---|--------------|
| Date Customer Must be Ready to Receive Post-Conversion Material: | Apr 16, 2007 |
|---|--------------|

Description of Change to the Customer:

1. As part of Intel's continuing commitment to enhance product quality and enhance manufacturability, an updated SIO device will be used.
2. Updated BIOS for improved system performance.
3. Improved board power design to increase compatibility robustness with wider range of power supply units.

Customer Impact of Change and Recommended Action:

The changes have been thoroughly evaluated to ensure there is no quality, reliability or functional impact to customers.

Products Affected / Intel Ordering Codes:

| Pre Change Product Code | Pre Change MM# | Pre Change AA | Pre Change PBA | Post Change AA | Post Change PBA |
|-------------------------|----------------|---------------|----------------|----------------|-----------------|
| BLKDG965WHMKR 878643 | 878643 | D41692-306 | D41688-306 | D41692-307 | D41688-307 |
| BOXDG965WHMKR 878646 | 878646 | D41692-306 | D41688-306 | D41692-307 | D41688-307 |

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:
March 28, 2007

Revision Number:
00

Reason:
Originally Published PCN