



Product Change Notification

Change Notification #: 815309-00

Change Title: Intel® D50DNP Server Family,
PCN 815309-00, Product Design,
Firmware Update

Date of Publication: February 05, 2024

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:*	February 21, 2024
--	-------------------

* Intel appreciates the customer's desire to receive the latest revision of products. However, Intel manages inventory on a first in first out (FIFO) basis at the MM# level. Subsequently, customer requests for a specific revision of material (below the MM#) will not be supported by Intel.

Description of Change to the Customer:

The firmware of the Intel SKUs listed in the products affected table will be updated to the new version supporting the 5th Gen Intel® Xeon® processors:

- BIOS : R01.02.0001
- BMC : 1.95
- CPLD : DNP V4P8
- FRU/SDR: DNP 0.09

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers. Please contact your local Intel Field Sales Representative if you have any further questions about these changes.

Products Affected/Intel Ordering Codes:

Marketing Name	Product Code	MM#	Pre Change TA	Pre Change SA	Pre Change PBA	Post Change TA	Post Change SA	Post Change PBA
Intel® Server Board D50DNP1SB	D50DNP1SB	99ARWL	M44397-451		M44241-452 M44241-462	M44397-452		M44241-453 M44241-463

Marketing Name	Product Code	MM#	Pre Change TA	Pre Change SA	Pre Change PBA	Post Change TA	Post Change SA	Post Change PBA
Intel® Server System D50DNP1MHCPCAC Compute Module	D50DNP1MHCPCAC	99ARWP	M65139-002	N12402-002		M65139-003	N12402-003	
Intel® Server System D50DNP2MHSVAC Management Module	D50DNP2MHSVAC	99ARWV	M65143-002	N12587-002		M65143-003	N12587-003	
Intel® Server System D50DNP2MFALAC Acceleration Module	D50DNP2MFALAC	99ARWX	M65146-003	N12586-003		M65146-004	N12586-004	
Intel® Server System D50DNP1MHCPLC Compute Module	D50DNP1MHCPLC	99ARWT	M65142-002	N12574-002		M65142-003	N12574-003	
Intel® Server System D50DNP1MHEVAC Compute Module	D50DNP1MHEVAC	99ARWR	M65141-002	N12584-002		M65141-003	N12584-003	
Intel® Server System D50DNP1MFALLC Acceleration Module	D50DNP1MFALLC	99ARWW	M65144-002	N12373-002		M65144-003	N12373-003	

PCN Revision History:

Date of Revision:
February 05, 2024

Revision Number:
00

Reason:
Originally Published PCN



Product Change Notification

815309-00

Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at www.intc.com.

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com