



# Product Change Notification

**Change Notification #:** 816910-00

**Change Title:** Select Intel® Ethernet Network Adapters  
PCN 816910-00, Product Design,  
Bracket Shipping Configuration Change

**Date of Publication:** February 29, 2024

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:


<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	April 08, 2024
---	----------------

## Description of Change to the Customer:




The Intel® SKUs listed in the products affected table below will have the following change(s):

- The bracket shipping configuration will change. These products will now ship with the Low-profile bracket installed on the adapter and the Full-height bracket loose in the clamshell pocket.

**Current X550T2G1P5 Configuration**







**New X550T2G1P5 Configuration**




**Current E810XXVDA4LG1P5 Configuration**



**New E810XXVDA4LG1P5 Configuration**




**Current I350T4G2P20 Configuration**






**New I350T4G2P20 Configuration**



**Current E810CQDA2G2P5 Configuration**






**New E810CQDA2G2P5 Configuration**



**Current E810CQDA1G1P5 Configuration**



**New E810CQDA1G1P5 Configuration**



As a result of these changes above, the Printed Board Assembly (PBA) and Top Assembly (TA) numbers will roll as noted in the affected products table within this PCN notice. The PBA for the products denoted with an asterisk (\*) in the affected products table will have a new PBA. If the PBA/TA numbers are printed on any product or box labels, those will show the new PBA/TA as well.

**Customer Impact of Change and Recommended Action:**

Intel anticipates no impact to customers. However, customers should be aware of the changes and take appropriate actions to accommodate the changes and avoid impact to their processes for receiving or integration in their factories.

Customers can expect to receive mixed inventory until current inventory levels are depleted.

Please contact your local Intel Field Sales Representative if you have any further questions about these changes.

**Products Affected/Intel Ordering Codes:**

Marketing Name	Product Code	MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
Intel® Ethernet Network Adapter E810-CQDA1	*E810CQDA1G1P5	978314	K70638-005	M17659-006	K70638-006	N45459-001
Intel® Ethernet Server Adapter I350-T4	I350T4G2P20	934608	H34230-007	H32730-007	H34230-008	H32730-008
Intel® Ethernet Converged Network Adapter X550-T2	X550T2G1P5	940263	H92727-004	H49289-013	H92727-005	H49289-014
Intel® Ethernet Network Adapter E810-XXVDA4	E810XXVDA4LG1P5	979091	K70877-006	M10767-008	K70877-007	M10767-009
Intel® Ethernet Network Adapter E810-CQDA2	*E810CQDA2G2P5	99A454	K99580-008	K91258-012	K99580-009	N45700-001

**PCN Revision History:**

<b>Date of Revision:</b> February 29, 2024	<b>Revision Number:</b> 00	<b>Reason:</b> Originally Published PCN
---	-------------------------------	--



# Product Change Notification

## 816910-00

### Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at [www.intc.com](http://www.intc.com).

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)