



# Product Change Notification

## 106699 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** <mailto:asmo.pcn@intel.com>

**Asia Pacific Contact:** <mailto:apacgccb@intel.com>

**Europe Email:** <mailto:eccb@intel.com>

**Japan Email:** <mailto:jccb.ijkk@intel.com>

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 106699 - 00  
**Change Title:** D945PWM, PCN 106699-00, Product Design, FIX REAR AUDIO MIC VOLUME  
**Date of Publication:** August 17, 2006

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Sep 14, 2006
<b>Date of First Availability of Post-Conversion Material:</b>	Sep 07, 2006

*The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.*

## Description of Change to the Customer:

Replace a transistor (Q8A1) to fix volume level on the rear microphone input.

## Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. UPSD is not recommending additional qualification of these changes on platforms received from Intel. These board changes are not expected to cause a change to the Microsoft\* Windows\* operating system's software driver stack. No expected OS image change.

## Products Affected / Intel Ordering Codes:

### Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA
BOXD945PWMML	879291	879291	D42248-101	D42248-102

## PCN Revision History:

<b>Date of Revision:</b> August 17, 2006	<b>Revision Number:</b> 00	<b>Reason:</b> Originally Published PCN
---	-------------------------------	--