



Product Change Notification

108388 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108388 - 00
Change Title: S5400SF, PCN 108388-00, Product Material, System BIOS Change
Date of Publication: April 01, 2008

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Apr 04, 2008
---	--------------

Description of Change to the Customer:

System BIOS is revving from R0024 to R0025

- A change was made to BIOS R0025 to correct a BIOS ID string issue present in BIOS R0024. The change was needed to address BIOS flash update issues seen while using Intel's Server Deployment Toolkit CDROM. Other BIOS update tools are not affected by this issue.

Customer Impact of Change and Recommended Action:

Intel anticipates no customer impact for this change

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
BB5400SF 892604	892604	E15540-404	D87491-404	E15540-405	D87491-405

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision: April 1, 2008	Revision Number: 00	Reason: Originally Published PCN
---	-------------------------------	--