



Product Change Notification

107689 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107689 - 00
Change Title: SR4850HW4M,SHW4URM3SA,SR6850HW4M and SHW6URM3SA, PCN 107689-00, Product Design, Class 2 Accessories: DVD-ROM changing
Date of Publication: June 26, 2007

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jul 06, 2007
---	--------------

Description of Change to the Customer:

Current QSI/Philips DVD-ROM going EOL, being replaced by QSI/Sony DVD-ROM

SR4850HW4M (SHW4URM)
MM 879454

Change top assembly part number from D35286-008 to D35286-009

SHW4URM3SA
MM 886995

Change top assembly part number from D46299-006 to D46299-007

SR6850HW4M (SHW6URM)
MM 879452

Change top assembly part number from D35289-006 to D35289-007

SHW6URM3SA
MM 887385

Change top assembly part number from D46296-006 to D46296-007

Customer Impact of Change and Recommended Action:

No significant impact on product/process/material performance, appearance, quality, reliability, interchangeability, functionality or customer handling and manufacturability.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change TA
SHW4URM	879454	D35286-008	D35286-009
SHW6URM	879452	D35289-006	D35289-007
SHW4URM3SA	886995	D46299-006	D46299-007

SHW6URM3SA	887385	D46296-006	D46296-007
------------	--------	------------	------------

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

June 26, 2007

00

Originally Published PCN