



# Product Change Notification

## 109336 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jcb.ijkk@intel.com](mailto:jcb.ijkk@intel.com)

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 109336 - 00  
**Change Title:** Intel (r) High Performance X25-M/X18-M  
MLC Solid-State Drive, PCN 109336-00,  
Product Design, Firmware Version Update to  
8820  
**Date of Publication:** April 13, 2009

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	May 04, 2009
---	--------------

## Description of Change to the Customer:

Intel is upgrading the firmware for its High Performance Solid-State MLC Drives (X25-M/X18-M) to version 8820. These changes are incremental improvements from previous firmware version. Inventory will transition in the Intel factory on or beyond the above date to replace older firmware version with 8820 version.

The following changes apply:

MM# 899855  
The SA# changes from E40124-903 to E40124-904

MM# 899854  
The SA# changes from E40124-903 to E40124-904

MM# 901776  
The SA# changes from E40124-903 to E40124-904

MM# 900344  
The SA# changes from E52670-903 to E52670-904

MM# 900343  
The SA# changes from E52670-903 to E52670-904

MM# 902958  
The SA# changes from E52670-903 to E52670-904

MM# 894401  
The SA# changes from E41502-302 to E41502-303

MM# 894400  
The SA# changes from E41502-302 to E41502-303

MM# 901461  
The SA# changes from E41502-302 to E41502-303

MM# 899389  
The SA# changes from E56491-702 to E56491-703

MM# 899388  
The SA# changes from E56491-702 to E56491-703

MM# 900328  
The SA# changes from E57723-903 to E57723-904

MM# 900341  
The SA# changes from E57723-903 to E57723-904

MM# 894103  
The SA# changes from E41496-903 to E41496-904

MM# 894125  
The SA# changes from E41496-903 to E41496-904

MM# 901460  
The SA# changes from E41496-903 to E41496-904

Please contact your Field Sales Personnel for Errata Report

### Customer Impact of Change and Recommended Action:

Since this firmware update is considered incremental, Intel anticipates no product impact with this firmware, and re-qualification is not recommended.

### Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change TA
SSDSA2MH080G101894103	894103	E41495-903	E41495-904
SSDSA2MH080G1 894125	894125	E41498-903	E41498-904
SSDSA1MH080G1 894400	894400	E41510-302	E41510-303
SSDSA1MH080G101894401	894401	E41499-302	E41499-303
SSDSA1MH160G101899388	899388	E56486-702	E56486-703
SSDSA1MH160G1 899389	899389	E56485-702	E56485-703
SSDSA2MH080G1C1899854	899854	E48766-903	E48766-904
SSDSA2MH080G1C5899855	899855	E48765-903	E48765-904
SSDSA2MH160G1 900328	900328	E52668-903	E52668-904
SSDSA2MH160G101900341	900341	E52671-903	E52671-904
SSDSA2MH160G1C5900343	900343	E52672-903	E52672-904
SSDSA2MH160G1C1900344	900344	E52673-903	E52673-904
SSDSA2MH080G105901460	901460	E57184-903	E57184-904
SSDSA1MH080G105901461	901461	E57185-702	E57185-703
SSDSA2MH080G1C 901776	901776	E59895-903	E59895-904
SSDSA2MH160G1C 902958	902958	E67159-903	E67159-904

**PCN Revision History:**

**Date of Revision:**

April 13, 2009

**Revision Number:**

00

**Reason:**

Originally Published PCN