



Product Change Notification

Change Notification #: 119231-00

Change Title: Select Intel® Server Board Products,
PCN 119231-00, Product Design,
Board FW Update from Factory

Date of Publication: August 24, 2022

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material	September 08, 2022
--	--------------------

Description of Change to the Customer:

The Intel SKUs listed in the products affected table will have the following firmware version changes.

	Current	New
BIOS	R01.01.003.factory	R01.01.005.factory
ME	04.04.04.53	04.04.04.62
BMC	2.81.99b20e11	2.88.e5f45b9c
SDR	0.35	0.40
CPLD	3p3	3p5

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers.

Please contact your local Intel Field Sales Representative if you have any further questions about these changes.

Products Affected/Intel Ordering Codes:

Marketing Name	Product Code	MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
Intel® Server Board M50CYP2SB1U, Single	M50CYP2SB1U	99A3TR	M56933-353	M57662-353	M56933-354	M57662-354
Intel® Server Board M50CYP2SBSTD, 5 Pack	M50CYP2SBSTD	99A5A0	M56932-353	M57661-353	M56932-354	M57661-354

PCN Revision History:**Date of Revision:**

August 24, 2022

Revision Number:

00

Reason:

Originally Published PCN



Product Change Notification

119231-00

Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at www.intc.com.

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com