



Product Change Notification

105363 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 105363 - 00
Change Title: SS7 Protocols, PCN 105363-00, PD,
Discontinuance of SS7 protocols that are
controlled by a manual licensing process
Date of Publication: September 1, 2005

Type of Change Notification:
PD - (Product Discontinuance)

Key Characteristics of the Change:
Software
Product Discontinuance

Forecasted Key Milestones:

Product Discontinuance Program Support Begins	Sep 01, 2005
Last Product Discontinuance Order Date:	Dec 31, 2005
Last Product Discontinuance Shipment Date:	Feb 04, 2006

Description of Change to the Customer:

Discontinuance of the SS7 protocols that are controlled by a manual licensing process. SS7 protocols are now available that are controlled by enforced licensing software. End user's should encounter no difference as the binary itself is not changing, just the way it is licensed.

Customer Impact of Change and Recommended Action:

These products will no longer be orderable, downloadable and no longer supported. Last Product Return Date is November 26, 2005. Orders are non-cancelable and non-returnable after November 26, 2005.

The SS7 protocols listed below will no longer be supported after December 30, 2006.

End of Support is defined as the date after which the following support services are no longer available:

- Software availability - download and ordering
- Telephone, email and web support for affected product(s)
 - Customers will be directed to migration product
- Active reproduction of customer-reported issues
- Installation and configuration support
- Technote and application note creation and maintenance
- Issue entry and tracking via issue management tool
- Defect entry. Fixes for unresolved defects will not be pursued nor released in Point or Service Packages, or in a product revision.

- No new Feature Requests will be accepted.

The End of Support date does not impact the terms of any stated hardware product warranty that governs product repair service.

Migration Path

Product Names	MM#	Migration Product	MM#
SS7SBS7L42WNT	842604	SS7SBHSTTUP	852886
SS7SBS7L43WNT	842607	SS7SBHSTISUP	852876
SS7SBS7L51WNT	842615	SS7SBHSTTCAP	852881
SS7SBS7L44SOL	842618	SS7SBHSTSCCPCL	852879
SS7SBS7L44LNX	842619	SS7SBHSTSCCPCL	852879
SS7SBS7L44WNT	842620	SS7SBHSTSCCPCL	852879
SS7SBS7L43LNX	842657	SS7SBHSTISUP	852876
SS7SBS7L43SOL	842658	SS7SBHSTISUP	852876
SS7SBS7L42LNX	842659	SS7SBHSTTUP	852886
SS7SBS7L42SOL	842660	SS7SBHSTTUP	852886
SS7SBS7L51LNX	842663	SS7SBHSTTCAP	852881
SS7SBS7L51SOL	842664	SS7SBHSTTCAP	852881
SS7SBS7L61WNT	842666	SS7SBHSTMAP	852878
SS7SBS7L61LNX	842667	SS7SBHSTMAP	852878
SS7SBS7L61SOL	842668	SS7SBHSTMAP	852878
SS7SBS7L62WNT	842670	SS7SBHSTIS41	852883
SS7SBS7L62LNX	842671	SS7SBHSTIS41	852883
SS7SBS7L62SOL	842672	SS7SBHSTIS41	852883
SS7SBS7L63WNT	842674	SS7SBHSTINAP	852884
SS7SBS7L63LNX	842675	SS7SBHSTINAP	852884
SS7SBS7L63SOL	842676	SS7SBHSTINAP	852884
SS7SBS7L33WNT	843600	SS7SBHSTMTP3	852875
SS7SBS7L33LNX	843601	SS7SBHSTMTP3	852875
SS7SBS7L33SOL	843602	SS7SBHSTMTP3	852875
SS7SBS7L63WNT	843890	SS7SBHSTINAP	852884
SS7SBS7L63LNX	843891	SS7SBHSTINAP	852884
SS7SBS7L63SOL	843893	SS7SBHSTINAP	852884

Contact your sales representative for migration information and/or any issues you may have with this End of Support Plan.

Products Affected / Intel Ordering Codes:

Software Product Table

Affected Product Code	Affected MM#
SS7SBS7L42WNT	842604
SS7SBS7L43WNT	842607
SS7SBS7L51WNT	842615
SS7SBS7L44SOL	842618
SS7SBS7L44LNX	842619
SS7SBS7L44WNT	842620
SS7SBS7L43LNX	842657
SS7SBS7L43SOL	842658

Affected Product Code	Affected MM#
SS7SBS7L42LNX	842659
SS7SBS7L42SOL	842660
SS7SBS7L51LNX	842663
SS7SBS7L51SOL	842664
SS7SBS7L61WNT	842666
SS7SBS7L61LNX	842667
SS7SBS7L61SOL	842668
SS7SBS7L62WNT	842670
SS7SBS7L62LNX	842671
SS7SBS7L62SOL	842672
SS7SBS7L63WNT	842674
SS7SBS7L63LNX	842675
SS7SBS7L63SOL	842676
SS7SBS7L33WNT	843600
SS7SBS7L33LNX	843601
SS7SBS7L33SOL	843602
SS7SBS7L63WNT	843890
SS7SBS7L63LNX	843891
SS7SBS7L63SOL	843893

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

September 1, 2005

Revision Number:

00

Reason:

Originally Published PCN