



Product Change Notification

#112580 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia/PRC Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2013. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trade Marks and Brands correctly at: <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 112580 - 00
Change Title: Intel® Anti-Theft Service Activation Code Cards, PCN 112580-00, Product Discontinuance
Date of Publication: September 25, 2013

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Product Discontinuance Program Support Begins:	September 25, 2013
Last Product Discontinuance Order Date:	October 25, 2013
Last Product Discontinuance Shipment Date:	November 8, 2013
Orders are Non-Cancelable and Non-Returnable After:	November 29, 2013

Description of Change to the Customer:

Market demand for the products listed in the "Products Affected/Intel Ordering Codes" table below have shifted to other Intel products. The products identified in this notification will be discontinued and unavailable for additional orders after the "Last Product Discontinuance Order Date" (see "Key Milestones" above).

Customer Impact of Change and Recommended Action:

Products listed in the "Products Affected/Intel Ordering Codes" table should be managed in accordance with the "Key Milestones" listed above. The "Last Product Discontinuance Order Date" is the final day for customers who carry backlog to book the orders Intel has granted as of the "Orders are Non-Cancellable and Non-Returnable After" (NCNR) date. The "Orders are Non-Cancellable and Non-Returnable After" date applies to all remaining backlog and/or orders after the "Last Product Discontinuance Order Date." From date of PCN publication, interim booking and turn back deadlines or separate Letter Agreements will apply vs. the standard Corporate Assurance Process.

The Intel Anti-Theft Service Activation cards listed in the "Products Affected/Intel Ordering Codes" table below will not be available after inventory is depleted (see "Key Milestones" above.)

Products Affected / Intel Ordering Codes:

Marketing Name	Product Code	MM#
Intel® Anti-Theft Service Activation Code Card 1 year	BXIATSC1YRENG	922072
Intel® Anti-Theft Service Activation Code Card 3 year	BXIATSC3YRENG	922073
Intel® Anti-Theft Service Activation Code Card 1 year	BXIATSC1YRENGFR	922074
Intel® Anti-Theft Service Activation Code Card 3 year	BXIATSC3YRENGFR	922075
Intel® Anti-Theft Service Activation Code Card 1 year	BXIATSC1YRENGGR	922278
Intel® Anti-Theft Service Activation Code Card 3 year	BXIATSC3YRENGGR	922279
Intel® Anti-Theft Service Activation Code Card 1 year	BXIATSC1YRRSN	922631
Intel® Anti-Theft Service Activation Code Card 3 year	BXIATSC3YRRSN	922632
Intel® Anti-Theft Service Activation Code Card 1 year	BXIATSC1YRKRN	922633
Intel® Anti-Theft Service Activation Code Card 3 year	BXIATSC3YRKRN	922634
Intel® Anti-Theft Service Activation Code Card 1 year	BXIATSC1YRENGIT	922635

Marketing Name	Product Code	MM#
Intel® Anti-Theft Service Activation Code Card 3 year	BXIATSC3YRENGIT	922637
Intel® Anti-Theft Service Activation Code Card 1 year	BXIATSC1YRSPBPR	922638
Intel® Anti-Theft Service Activation Code Card 3 year	BXIATSC3YRSPBPR	922639
Intel® Anti-Theft Service Activation Code Card 1 year	BXIATSC1YRCHN	922640
Intel® Anti-Theft Service Activation Code Card 3 year	BXIATSC3YRCHN	922641
Intel® Anti-Theft Service Activation Code Card 1 year	BXIATSC1YRJPN	922642
Intel® Anti-Theft Service Activation Code Card 3 year	BXIATSC3YRJPN	922643
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRSWDFIN	924240
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRSWDFIN	924241
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRARBFRE	924242
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRARBFRE	924243
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRHUNPOL	924244
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRHUNPOL	924245
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRTURK	924246
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRTURK	924247
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRSPNPOR	924249
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRSPNPOR	924250
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRNORDAN	924251
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRNORDAN	924252
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRCZHSLV	924253
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRCZHSLV	924254
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRENGDUT	924255
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRENGDUT	924256
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRHBRW	924257
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRHBRW	924258
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRCROSRB	924260
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRCROSRB	924261
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRGRK	924759
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRGRK	924760
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRENG	924761
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRENG	924762
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRENGGER	924763
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRENGGER	924764
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRENGFR	924765
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRENGFR	924766
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRSPNBRZ	924767
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRSPNBRZ	924768
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRENGIT	925645
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRENGIT	925646
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRCHN	925648
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRCHN	925649
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRJPN	925650
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRJPN	925651
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRKRN	925652
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRKRN	925653
Intel® Anti-Theft Service 2.0 Activation	BXIATS1YRRUS	925654
Intel® Anti-Theft Service 2.0 Activation	BXIATS3YRRUS	925655

PCN Revision History:

Date of Revision:

September 25, 2013

Revision Number:

00

Reason:

Originally Published PCN