



Product Change Notification

107497 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107497 - 00
Change Title: DG965OT, PCN 107497-00, Product Design, Bios update, improved SATA cable and adding alternate component to support manufacturability
Date of Publication: April 20, 2007

Key Characteristics of the Change:
 Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	May 03, 2007
---	--------------

Description of Change to the Customer:

- As part of Intel's continuing commitment to enhance product quality and enhance manufacturability, an updated SIO device will be used.
- Updated BIOS for improved system performance.
- Single-latch SATA cable replaced with dual-latch SATA cable design to minimize possibility of cables becoming detached from hard disk devices. For BOX and BLK SKUs only.

Customer Impact of Change and Recommended Action:

The changes have been thoroughly evaluated to ensure that there is no quality, reliability or functional impact to customers.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change AA	Pre Change PBA	Post Change TA	Post Change AA	Post Change PBA
LADG965OTKR 878116	878116	N/A	D41021-205	D41028-205	N/A	D41021-206	D41028-206
BOXDG965OTMKR 885058	885058	D63658-105	D63733-205	D63732-205	D63658-106	D63733-206	D63732-206
BLKDG965OTMKR 885059	885059	D63657-105	D63733-205	D63732-205	D63657-106	D63733-206	D63732-206

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:
April 20, 2007

Revision Number:
00

Reason:
Originally Published PCN