



# Product Change Notification

**Change Notification #:** 115186 - 00  
**Change Title:** Select Intel® XWAY™ SLICS PEF42642 SLIC, Intel® XWAY™ SmartSLIC, Intel® DUSLIC™ XS1 PEF32001 Codec, Intel® DUSLIC™ xT1 PEF3101 Codec, PEF42068 SLIC, PCN 115186-00, Product Discontinuance, Discontinuance of some SLIC/DuSLIC versions  
**Date of Publication:** December 16, 2016

**Key Characteristics of the Change:**  
Product Discontinuance

## Forecasted Key Milestones:

<b>Product Discontinuance Program Support Begins:</b>	December 16, 2016
<b>Last Product Discontinuance Order Date:</b>	June 30, 2017
<b>Last Product Discontinuance Shipment Date:</b>	December 31, 2017

**Description of Change to the Customer:** Select Intel® XWAY™ SLICS PEF42642 SLIC, MM#946250, Intel® XWAY™ SmartSLIC PEF42068 SLIC, MM#946792, Intel® DUSLIC™ XS1 PEF32001 Codec, MM#946831 and, Intel® DUSLIC™ xT1 PEF3101 Codec, MM#946827 will end of life.

## Customer Impact of Change and Recommended Action:

Customers should place their Last Time Orders by June 30, 2017 and delivery of all orders must be taken no later than December 31, 2017.

Please use the recommended replacement skus as shown on the Products Affected/Intel Ordering Codes table below:

- Intel® XWAY™ SLICE PEF42652 SLIC, PEF42652VV22 MM#952813
- Intel® XWAY™ SmartSLIC PEF42078 SLIC, PEF42078VTV11 MM#947705
- Intel® DUSLIC™ XC1 PEF31001 Codec, PEF32001VSV12 MM#950949
- Intel® DUSLIC™ XC1 PEF31001 Codec, PEF32001VTV12 MM#950947

Milestone dates are estimates and subject to change based on business and operational conditions.

Please contact your local Intel Field Sales Representative if you have any further questions about this End of Life notice.

## Products Affected / Intel Ordering Codes:

Product Name	Product Code	MM#	Recommended Replacement Product Code	Recommended Replacement MM#
Intel® XWAY™ SLICS PEF42642 SLIC	PEF42642TV21	946250	PEF42652VV22	952813
Intel® XWAY™ SmartSLIC PEF42068 SLIC	PEF42068FV12	946792	PEF42078VTV11	947705
Intel® DUSLIC™ xT1 PEF3101 Codec	PEF3101VV14	946827	PEF32001VSV12	950949
Intel® DUSLIC™ XS1 PEF32001 Codec	PEF32001VTV11	946831	PEF32001VTV12	950947

## PCN Revision History:

**Date of Revision:**

December 16, 2016

**Revision Number:**

00

**Reason:**

Originally Published PCN



# Product Change Notification

## 115186 - 00

**INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apagccb@intel.com](mailto:apagccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2016. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.