



# Product Change Notification

## 107586 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 107586 - 00  
**Change Title:** SHW4URM23,SHW6URM23 and SHW4URM2SA23, PCN 107586-00, Product Design, Class 2:Accessories, AHWIMMPRO2 redesign  
**Date of Publication:** May 23, 2007

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

|   |              |
|---|--------------|
| <b>Date Customer Must be Ready to Receive Post-Conversion Material:</b> | Jun 29, 2007 |
|---|--------------|

## Description of Change to the Customer:

The IMM Professional is being redesigned to ensure the IMM Professional to meet the BMC chipset specification requirements for power up sequencing of the BMC chipset. There are no known issues relating to the power sequencing of the BMC with former design. BMC firmware will be updated.

SHW4URM23

MM# 886993

Change top assembly part number -will be added when available  
Change the IMM Board part number from D23013-452 to D23013-701

SHW6URM23

MM# 886994

Change top assembly part number -will be added when available  
Change the IMM Board part number from D23013-452 to D23013-701

SHW4URM2SA23

MM# 885102

Change top assembly part number -will be added when available  
Change the IMM Board part number from D23013-452 to D23013-701

## Customer Impact of Change and Recommended Action:

No significant impact on product/process/material performance, appearance, quality, reliability, interchangeability, functionality or customer handling and manufacturability.

## Products Affected / Intel Ordering Codes:

| <b>Pre Change<br/>Product Code</b> | <b>Pre Change<br/>MM#</b> | <b>Pre Change<br/>TA</b> | <b>Pre Change<br/>PBA</b> | <b>Post Change<br/>MM#</b> | <b>Post Change<br/>TA</b> | <b>Post Change<br/>PBA</b> |
|------------------------------------|---------------------------|--------------------------|---------------------------|----------------------------|---------------------------|----------------------------|
| AHWIMMPRO2                         | 878718                    | D42646-001               | D23013-452                | 885896                     | D42646-004                | D23013-701                 |
| SHW4URM2SA23                       | 885102                    | N/A                      | N/A                       | N/A                        |                           | N/A                        |
| SHW4URM23                          | 886993                    | N/A                      | N/A                       | N/A                        |                           | N/A                        |
| SHW6URM23                          | 886994                    | N/A                      | N/A                       | N/A                        |                           | N/A                        |

### **Reference Documents / Attachments:**

**Document:**

**Location #:**

### **PCN Revision History:**

**Date of Revision:**

May 23, 2007

**Revision Number:**

00

**Reason:**

Originally Published PCN