



Product Change Notification

108449 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108449 - 00
Change Title: Intel(R) Server System S7000FC4UR, PCN 108449-00, Product Design, Class 1, SAS Riser Firmware Update and Improvement to circuit for IBBU
Date of Publication: May 07, 2008

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jul 06, 2008
---	--------------

Description of Change to the Customer:

- SAS Riser Firmware update to new Integrated Dual Mode RAID Firmware, HWRAID Firmware Package = 8.0.1-0021 (FW 1.12.42-0352).
- Improvement to timing margin for IBBU circuit. See the May Specification Update when available for further details.

FFCSASRISER Rev 01	Roll to Rev 02
MM# 891493 Rev 03	Replace with New MM 898557
TA D64059-304 Rev 01	Roll dash to D64059-305
PBA D56622-304	Roll dash to D56622-305

Customer Impact of Change and Recommended Action:

Date to implement is non-standard; customers may receive these components earlier than the specified date.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
FFCSASRISER	891493	D64059-304	D56622-304	898557	D64059-305	D56622-305

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:

May 7, 2008

Revision Number:

00

Reason:

Originally Published PCN