



Product Change Notification

106687 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106687 - 02
Change Title: SC5250-E, PCN 106687-02, Product Discontinuance, Class 1, Product Discontinuance Announcement, Reason for Revision: Error in Subassembly information for AXX2HSDRVUG
Date of Publication: August 23, 2006

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Last Product Discontinuance Order Date:	Aug 17, 2006
Last Product Discontinuance Shipment Date:	Aug 17, 2006

Description of Change to the Customer:

Reason for Revision: Error in Subassembly information for AXX2HSDRVUG

Intel is announcing the discontinuance of the Intel® Entry Server Chassis SC5250-E and associated spares and accessories.

This notification affects the product codes included in the list below:

Intel(R) Entry Server Chassis:

-KPTBASE450
-KPTBASE450NA
-KPTBASE450BLK
-KPTBASE450BLKNA

Related Spares and Accessories:

-AXX2HSDRVUG
-FPTPMKIT
-ASATAHSDB

1. This product discontinuance announcement is effective immediately (August 17, 2006).
2. The products mentioned above are not RoHS compliant (regulatory) and can no longer be sold in Europe.
3. All server boards supported with the above chassis/accessories are already in an EOL status.

Customer Impact of Change and Recommended Action:

Since the boards supported with the above chassis/accessories are considered to be in an EOL status, no impact to our customers is projected.

Please contact your local Intel Sales Office or Distributor if you require more information or need assistance in selecting a replacement product.

Products Affected / Intel Ordering Codes:

Component Product Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
KPTBASE450	852511	852511	C25405-004	C25405-004	C25318-002	C25318-002
KPTBASE450	853718	853718	C25405-008	C25405-008	C25318-003	C25318-003
KPTBASE450	858478	858478	C25405-016	C25405-016	C25318-009	C25318-009

Component Product Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
KPTBASE450NA	854463	854463	C25405-008	C25405-008	C25318-003	C25318-003
KPTBASE450NA	858513	858513	C25405-016	C25405-016	C25318-009	C25318-009

Component Product Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
KPTBASE450BLK	852295	852295	C25402-004	C25402-004	C25232-002	C25232-002
KPTBASE450BLK	853719	853719	C25402-008	C25402-008	C25232-003	C25232-003
KPTBASE450BLK	858479	858479	C25402-016	C25402-016	C25232-009	C25232-009

Component Product Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
KPTBASE450BLKNA	854465	854465	C25402-008	C25402-008	C25232-003	C25232-003
KPTBASE450BLKNA	858511	858511	C25402-016	C25402-016	C25232-009	C25232-009

Component Product Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
ASATAHSDB	853276	853276	C32597-002	C32597-002	C41860-002	C41860-002
AXX2HSDRVUG	835948	835948	A53803-006	A53803-006	A49517-006	A49517-006
FPTPMKIT	852425	852425	C26797-004	C26797-004	C26802-102	C26802-102

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

August 14, 2006

Revision Number:

00

Reason:

Originally Published PCN

August 17, 2006

August 23, 2006

01

02

Product No Longer Being Built
Error in Subassembly information
for AXX2HSDRVUG