



Product Change Notification

108270 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108270 - 00
Change Title: Intel Server Spare Parts, PCN 108270-00, Product Discontinuance, Replacement of TMWPCIERSR01W with ABKPCIEXPUP and TMWPCIXRSR01W with ABKPCIXUP
Date of Publication: February 22, 2008

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Last Product Discontinuance Order Date:	Feb 15, 2008
Last Product Discontinuance Shipment Date:	Feb 15, 2008

Description of Change to the Customer:

Pcode TMWPCIERSR01W MM# 886490 replaced by Pcode ABKPCIEXPUP MM# 878705
Pcode TMWPCIXRSR01W MM# 886491 replaced by Pcode ABKPCIXUP MM# 878706

The TMW parts each included 2 x mounting screws, which are not in the ABK kits. These screws are already included in the server chassis and were redundant. The riser board assembly is identical.

Customer Impact of Change and Recommended Action:

This change has been tested and passed a validation cycle on the Intel® Carrier Grade Server TIGW1U and Intel® IP Network Server NSW1U.

No testing is required, as the same physical riser board is in both the previous and replacement part.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Recommended Replacement Product Code	Recommended Replacement MM#
TMWPCIERSR01W	886490	ABKPCIEXPUP	878705
TMWPCIXRSR01W	886491	ABKPCIXUP	878706

PCN Revision History:

Date of Revision: February 22, 2008	Revision Number: 00	Reason: Originally Published PCN
---	-------------------------------	--

