



Product Change Notification

Change Notification #: 119033-01

Change Title: Select Intel® Ethernet Network Adapter E810-2CQDA2,
Intel® Ethernet Network Adapter E810-CQDA2,
Intel® Ethernet Network Adapter OCP3.0 E810-CQDA2,
Intel® Ethernet Network Adapter OCP3.0 E810-XXVDA2,
Intel® Ethernet Network Adapter OCP3.0 E810-XXVDA4,
Intel® Ethernet Network Adapter OCP3.0 E810-CQDA1,
Intel® Ethernet Network Adapter E810-XXVDA4,
Intel® Ethernet Network Adapter E810-XXVDA2,
Intel® Ethernet Network Adapter E810-CQDA2,
Intel® Ethernet Network Adapter E810-CQDA1,
PCN 119033-01, Product Design,
NVM update to v3.2 and OUI update
Reason for Revision: Updating one affected SKU in the table under bullet #2, and including additional Regulatory Marking Label Changes for the affected SKUs in bullet #3 under the “Description of Change to the Customer”

Date of Publication: August 14, 2023

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material	June 14, 2022
--	---------------

Description of Change to the Customer:

Updating one affected SKU in the table under bullet #2, and including additional Regulatory Marking Label Changes for the affected SKUs in bullet #3 under the, “Description of Change to the Customer”

The following describes the changes being made:


1. Intel will update the NVM (non-volatile memory) image being programmed onto these cards to the latest NVM v3.2 for the PCIe adapters.
 - a. v3.2 has several added features: See Intel® Ethernet Controller E810 Feature Support Matrix for more details ([Intel® Ethernet Controller E810 Feature Support Matrix](#))
 - b. Customers who wish to update their older boards to the new NVM v3.2 can access the NVM update package here:
 - Start with this link: <https://downloadcenter.intel.com/product/184846/Intel-Ethernet-Network-Adapter-E810-Series>
 - Then, select the “Non-Volatile Memory (NVM) Update Utility for Intel® Ethernet Network Adapter E810 Series.
2. In addition to the change above, Intel will implement an OUI update from J40322 (B4-96-91) to M73264 (30-3E-A7) due to low watermark for these SKUs only:

Product code	MM#
E810XXVDA2OCPV3	983262
E810XXVDA2OCP3G	983263
E810XXVDA2OCP3L	99A0FV
E810CQDA1BLK	978313
E810CQDA1G1P5	978314
E810CQDA1	978312

3. In addition to the change above, Intel will implement a Regulatory label marking change to the following SKU's. The change adds the UKCA marking (See below)

Product code	MM#
E810CQDA2OCPV3G	983094
E810CQDA2OCPV3L	99A0FX
E810CQDA1OCPV3G	983093
E810CQDA1OCPV3L	99A01J
E810CQDA1OCPV3	983092
E810CQDA2OCPV3	983581

Previous Label



New Label



Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers.

Customers can expect to receive mixed inventory until current inventory levels are depleted.

Please contact your local Intel Field Sales Rep if you have any further questions about these changes.

Products Affected/Intel Ordering Codes:

Marketing Name	Product Code	MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
Intel® Ethernet Network Adapter E810-CQDA1, Retail Unit	E810CQDA1	978312	K70648-003	M17659-004	K70648-004	M17659-005
Intel® Ethernet Network Adapter E810-CQDA1, Retail Bulk	E810CQDA1BLK	978313	K70661-003	M17659-004	K70661-004	M17659-005
Intel® Ethernet Network Adapter E810-CQDA1, OEM Gen	E810CQDA1G1P5	978314	K70638-003	M17659-004	K70638-004	M17659-005
Intel® Ethernet Network Adapter E810-CQDA2, Retail Unit	E810CQDA2	978322	K66680-006	K91258-010	K66680-007	K91258-011
Intel® Ethernet Network Adapter E810-CQDA2, Retail Bulk	E810CQDA2BLK	978323	K66682-006	K91258-010	K66682-007	K91258-011
Intel® Ethernet Network Adapter E810-XXVDA2, Retail Unit	E810XXVDA2	978331	K94720-004	K57775-012	K94720-005	K57775-013
Intel® Ethernet Network Adapter E810-XXVDA2, Retail Bulk	E810XXVDA2BLK	978332	K94721-004	K57775-012	K94721-005	K57775-013
Intel® Ethernet Network Adapter E810-XXVDA2, OEM Gen	E810XXVDA2G1P5	978333	K65116-005	K57775-012	K65116-006	K57775-013
Intel® Ethernet Network Adapter E810-XXVDA4, Retail Unit	E810XXVDA4	978334	K66696-005	K92046-009	K66696-006	K92046-010
Intel® Ethernet Network Adapter E810-XXVDA4, Retail Bulk	E810XXVDA4BLK	978335	K66699-005	K92046-009	K66699-006	K92046-010
Intel® Ethernet Network Adapter E810-XXVDA4, OEM Gen	E810XXVDA4LG1P5	979091	K70877-004	M10767-006	K70877-005	M10767-007

Marketing Name	Product Code	MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
Intel® Ethernet Network Adapter OCP3.0 E810-CQDA1, Retail Unit	E810CQDA1OCPV3	983092	K59876-003	K98494-004	K59876-004	K98494-005
Intel® Ethernet Network Adapter OCP3.0 E810-CQDA1, OEM Gen	E810CQDA1OCPV3G	983093	K59871-003	M17434-004	K59871-004	M17434-004
Intel® Ethernet Network Adapter OCP3.0 E810-CQDA2, OEM Gen	E810CQDA2OCPV3G	983094	K57389-005	M12947-005	K57389-006	M12947-006
Intel® Ethernet Network Adapter OCP3.0 E810-XXVDA4, Retail Unit	E810XXVDA4OCPV3	983099	M33397-001	M33399-002	M33397-002	M33399-002
Intel® Ethernet Network Adapter OCP3.0 E810-XXVDA4, OEM Gen	E810XXVDA4OCP3G	983100	M33395-001	K80838-005	M33395-002	K80838-006
Intel® Ethernet Network Adapter OCP3.0 E810-XXVDA2, Retail Unit	E810XXVDA2OCPV3	983262	K94704-004	K71121-004	K94704-005	K71121-005
Intel® Ethernet Network Adapter OCP3.0 E810-XXVDA2, OEM Gen	E810XXVDA2OCP3G	983263	K65520-005	K58132-014	K65520-006	K58132-015
Intel® Ethernet Network Adapter OCP3.0 E810-CQDA2, Retail Unit	E810CQDA2OCPV3	983581	K59857-004	K98472-005	K59857-005	K98472-006
Intel® Ethernet Network Adapter OCP3.0 E810-CQDA1, OEM Gen	E810CQDA1OCPV3L	99A01J	K98482-003	K98484-004	K98482-004	K98484-005
Intel® Ethernet Network Adapter OCP3.0 E810-XXVDA4, OEM Gen	E810XXVDA4OCP3L	99A08T	M33396-001	M33398-002	M33396-002	M33398-002
Intel® Ethernet Network Adapter OCP3.0 E810-XXVDA2, OEM Gen	E810XXVDA2OCP3L	99A0FV	K93403-004	K87347-005	K93403-005	K87347-006
Intel® Ethernet Network Adapter OCP3.0 E810-CQDA2, OEM Gen	E810CQDA2OCPV3L	99A0FX	K98456-004	K98464-005	K98456-005	K98464-006
Intel® Ethernet Network Adapter E810-2CQDA2, OEM Gen	E8102CQDA2G1P5	99A13V	M31332-003	K87758-008	M31332-004	K87758-009
Intel® Ethernet Network Adapter E810-XXVDA4, OEM Gen	E810XXVDA4G2P5	99A2H8	K99581-005	K92046-009	K99581-006	K92046-010
Intel® Ethernet Network Adapter E810-CQDA2, OEM Gen	E810CQDA2G2P5	99A454	K99580-006	K91258-010	K99580-007	K91258-011
Intel® Ethernet Network Adapter E810-2CQDA2, Retail	E8102CQDA2	99AL14	M44778-002	K87758-008	M44778-003	K87758-009

PCN Revision History:

Date of Revision: Revision Number: Reason:

April 19, 2022 00

Originally Published PCN

August 14, 2023 01

Updating one affected SKU in the table under bullet #2, and including additional Regulatory Marking Label Changes for the affected SKUs in bullet #3 under the “Description of Change to the Customer”



Product Change Notification

119033-01

Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at www.intc.com.

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com