



Product Change Notification

106841 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106841 - 01
Change Title: SR1530AH, SR1530AHLX, SR1530AHNA and SR1530AHLXNA, PCN 106841-01, Product Material, Class 1, Replace server board with D66619-002/D66621-002, and chassis front panel board replacement, Reason for Revision: Correcting MM numbers.
Date of Publication: October 05, 2006

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Nov 10, 2006
---	--------------

Description of Change to the Customer:

Reason for Revision: Correcting MM numbers.

The Intel(r) SR1530AH and SR1530AHLX server systems are updated with the latest version of the Intel(r) S3000AH and S3000AHLX server boards. Changes to the board include the latest BIOS version and the Intel S3000AH board Intel NIC 82573V is replaced with the Intel 82573E NIC. See PCN 106773-01 and PCN106772-00 for additional details to the board change. The SR1530AH and SR1530AHLX systems will also include an updated front panel, PN# D51933-302 will be replaced with D51933-401. The system resource CD and Intel Server Manager 1.5 CDs have been updated. This change notification could not be posted in the normal guidelines due to factory changes to the system boards.

Customer Impact of Change and Recommended Action:

Evaluate the product when received

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change MM#	Post Change TA
SR1530AH 885366	885366	D66619-001	885366	D66619-002
SR1530AHLX 885367	885367	D66621-001	885367	D66621-002
SR1530AHLXNA 885450	885450	D66621-001	885450	D66621-002

SR1530AHNA 885449	885449	D66619-001	885449	D66619-002
----------------------	--------	------------	--------	------------

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

October 4, 2006

00

Originally Published PCN

October 5, 2006

01

Correcting MM numbers.