



Product Change Notification

110191 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2010. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 110191 - 00
Change Title: Intel® Celeron® Processor P1053, and Intel® Xeon® Processors EC5549, LC5518, LC3528, LC3518, EC5539, EC5509, EC3539, LC5528, and LC3538, PCN 110191-00, Product Marking, Removal of “i” from beginning of Processor Name
Date of Publication: August 27, 2010

Key Characteristics of the Change:

Product Marking


Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 02, 2010
-------------------------------------------------------------------------	--------------


Description of Change to the Customer:

The topside mark will be modified to remove the “i” on the processors listed in the Products Affected table below. This “i” is not part of the processor number and will be removed going forward.

OLD MARK



NEW MARK



Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers. There are no functional differences between processors marked with an “i” and those marked without it. While we are switching to the new mark you may receive some processors with the “i” and some without it.

Products Affected / Intel Ordering Codes:

Marketing Name	Processor#	Frequency (GHZ)	Stepping	Product Code	S-Spec	MM#
Intel® Xeon® Processor EC5549	EC5549	2.53	B	AT80612005712ABS	S LBWP	907831
Intel® Xeon® Processor LC5518	LC5518	1.73	B	AT80612002928ACS	S LBWF	907832
Intel® Xeon® Processor LC3528	LC3528	1.73	B	AT80612002931ABS	S LBWG	907833
Intel® Xeon® Processor LC3518	LC3518	1.73	B	AT80612002946AAS	S LBWH	907834
Intel® Xeon® Processor EC5539	EC5539	2.27	B	AT80612003861ABS	S LBWL	907835
Intel® Celeron® Processor P1053	P1053	1.33	B	AT80612004743AAS	S LBWN	907836
Intel® Xeon® Processor EC5509	EC5509	2.00	B	AT80612004740AAS	S LBWM	907837
Intel® Xeon® Processor EC3539	EC3539	2.13	B	AT80612003090AAS	S LBWJ	907838
Intel® Xeon® Processor LC5528	LC5528	2.13	B	AT80612003858AAS	S LBWK	907839
Intel® Xeon® Processor LC3538	LC3538	1.73	B	AT80612006669AAS	S LBYJ	908213

PCN Revision History:

Date of Revision:

August 27, 2010

Revision Number:

00

Reason:

Originally Published PCN