



Product Change Notification

110180 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2010. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 110180 - 00
Change Title: Intel (R) Server System SR1560SFHS, PCN 110180-00, Product Design, Remove Intel(R) System Management software DVD, Update Resource CD and Attention Document, Update Regulatory Label on packaging box and Safety Label on chassis
Date of Publication: August 10, 2010

Key Characteristics of the Change:

Product Design





Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 24, 2010
---	--------------

Description of Change to the Customer:

Intel will implement the following changes on the Intel(R) Server System SR1560SFHS and SR1560SFHSNA:

1. Updating the resource CD from D97784-006 to D97784-008 to include new drivers, documentation and software license document;
2. Removing the Intel® System Management Software DVD;
3. Updating attention document from D92939-003 to D92939-005 to include the latest software license agreement;
4. Updating the Regulatory Label on the packaging box to remove the China Compulsory Certification (CCC) mark and the Belarus mark; adding the "Circle 20" China Environmental Friendly Use Period (EFUP) mark and changing the Korean certification mark from MIC to KCC. The following are pictures of the prior and post change Regulatory Labels:

Prior change Regulatory Label	Post change Regulatory Label
 <p>この装置は、クラス A 情報技術装置です。この装置を家庭環境で使用すると電波妨害を引き起こすことがあります。この場合には使用者が適切な対策を講ずるよう要求されることがあります。VCCI-A</p> <p>This device complies with Part 15 of the FCC Rules. Operation of this device is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.</p> <p>CANADA ICES-003 CLASS A</p> <p>017938-002</p> 	 <p>この装置は、クラス A 情報技術装置です。この装置を家庭環境で使用すると電波妨害を引き起こすことがあります。この場合には使用者が適切な対策を講ずるよう要求されることがあります。VCCI-A</p> <p>This device complies with Part 15 of the FCC Rules. Operation of this device is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.</p> <p>CANADA ICES-003 CLASS A</p> <p>D52938-005</p> 

5. Updating the Safety Label on the Chassis to remove the China Compulsory Certification (CCC) mark and the Belarus mark; removing

Chinese text: **服务器** that states "server"; changing the Korean certification mark from MIC to KCC. The following are pictures of the prior and post change Safety Labels:

Prior change Safety Label	Post change Safety Label
<p>This device complies with Part 15 of the FCC Rules. Operation of this device is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.</p> <p>CANADA ICES-003 CLASS A Intel Corporation</p> <p>この装置は、クラスA情報技術装置です。この装置を家庭環境で使用すると電波妨害を引き起こすことがあります。この場合には使用者が適切な対策を講ずるよう要求されることがあります。 VCCI-A</p> <p>警告使用者： これは甲類の資訊產品、在居住的環境中使用時、可能會造成射頻干擾，在這種情況下，使用者會被要求採取某些適當的對策。</p> <p>声明 此为A级产品，在生活环境中，该产品可能会造成无线电干扰。在这种情况下，可能需要用户对干扰采取可行的措施。</p>  <p>100-127/200-240Vac ~, 50/60Hz, 7/3.5A</p> <p>1810B0043103 SR1560SF 服务器 MADE IN CHINA 中国制造 IPT</p>	<p>This device complies with Part 15 of the FCC Rules. Operation of this device is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.</p> <p>CANADA ICES-003 CLASS A Intel Corporation</p> <p>この装置は、クラスA情報技術装置です。この装置を家庭環境で使用すると電波妨害を引き起こすことがあります。この場合には使用者が適切な対策を講ずるよう要求されることがあります。 VCCI-A</p> <p>警告使用者： これは甲類の資訊產品、在居住的環境中使用時、可能會造成射頻干擾，在這種情況下，使用者會被要求採取某些適當的對策。</p> <p>声明 此为A级产品，在生活环境中，该产品可能会造成无线电干扰。在这种情况下，可能需要用户对干扰采取可行的措施。</p>  <p>100-127/200-240Vac ~, 50/60Hz, 7/3.5A</p> <p>1810B0043104 SR1560SF MADE IN CHINA 中国制造 IPT</p>

Effective August 31, 2010, Intel will no longer obtain or sustain the China CCC certifications on Intel's server sub-assembly chassis products. These products do not fall into the scope or catalogue of products requiring China CCC certifications; as these products are considered not fully integrated and are completely non-operational (e.g. no peripheral drives, memory, processors, add-in cards, etc). Please contact your local Intel representative if you have any questions regarding this notice.

Remove the Chinese text that states "server" is to avoid the misunderstanding that these products fall into the scope or catalogue of products requiring China CCC certifications.

This WEEE mark change is for the German scope interpretation of WEEE. WEEE is the European Union (EU) Directive regarding waste management of electrical and electronic equipment. Please refer the following link for more information about Intel's WEEE Directive Recycling Program:

<http://www3.intel.com/cd/channel/reseller/emea/eng/316697.htm>

The Belarus certification is not required until January 1, 2011 thus Intel decided to not apply / maintain the Belarus certification at this time. This Belarus mark removal will not affect any import to Belarus.

The current Korean certifications are still valid. The Korean certifier changed the Korean certification mark from MIC to KCC and requested certification holders to update the marking at their earliest convenience.

Customer Impact of Change and Recommended Action:

Customers can download the Intel® System Management Software DVD software from the Intel support web site: <http://www.intel.com/support>. Intel will continue to support the Intel® System Management Software on these server boards.

Customers may need to determine the need for the China Compulsory Certification (CCC) on their products before they are exported to or sold in the Peoples Republic of China market.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change MM#	Post Change TA
SR1560SFHS	901845	D94837-011	901845	D94837-012
SR1560SFHSNA	901872	D94837-011	901872	D94837-012

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision: August 10, 2010	Revision Number: 00	Reason: Originally Published PCN
---	-------------------------------	--