



Product Change Notification

104374 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geography location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2004. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 104374 - 00
Change Title: DMT9604T1PCIU, DMV4804T1PCIU, PCN 104374-00, FYI, Revise Firmware to correct board ID
Date of Publication: September 15, 2004

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 24, 2004
Date of First Availability of Post-Conversion Material:	Sep 24, 2004

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

Reprogrammed Flash Memory configuration files to correct board ID as read by DCM software (Windows) or configuration software for Linux. For the DMV4804T1PCIU board ID changed from "DM/V960-4T1" to "DM/V480-4T1". For the DMT9604T1PCIU board ID changed from "DM/V960-4T1" to "DM/T960-4T1".

Customer Impact of Change and Recommended Action:

Previous to the change the DCM software (Windows) and configuration software for Linux would incorrectly recognize the DMT9604T1PCIU board as a DMV9604T1PCIU or the DMV4804T1PCIU board as a DMV9604T1PCIU. This resulted in consignment of unused resources and general confusion.

Intel is providing customers with an option to update existing products in the field via the DRA process (repair and return).

Identifying boards that need updating:

Top Assembly (TA) number or Configured Assembly (CA) number

The TA number is located on the shipping box. If the TA number is 99-1742-001 or 99-1741-001 the board requires an update.

The CA number label is located on the board. If the CA number is 96-1140-001 or 96-1139-001 the board requires an update.

To return a board for an update:

US Distributors: Please fill out the online DRA form, mentioning "DM/T Firmware Update" or "DM/V Firmware Update" in the problem description field, at:

<http://www.intel.com/support/motherboards/draform.htm>

Non-US Distributors: Please contact your RMA Call Center to arrange for return and upgrade.

See order code details below.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Affected MM#	Pre change TA #	Post change TA #	Pre change CA #	Post change CA #
DMT9604T1PCIU	851028	99-1742-001	C84145-001	96-1140-001	C84144-001
DMV4804T1PCIU	851027	99-1741-001	C84142-001	96-1139-001	C84141-001

Reference Documents / Attachments:

Document:

Location #:

DRA Form

<http://www.intel.com/support/motherboards/draform.htm>

PCN Revision History:

Date of Revision:

September 15, 2004

Revision Number:

00

Reason:

Originally Published PCN