



# Product Change Notification

## 106931 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #: 106931 - 01**

**Change Title: D945PLNM, PCN 106931-01,  
Product Design, BIOS UPDATE  
WITH CHRISTEA 2.0.4, Reason  
for Revision: Schedule change**

**Date of Publication: November 22, 2006**

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Dec 07, 2006
---	--------------

## Description of Change to the Customer:

### Reason for Revision: Schedule change

The D945PLNM desktop board is being upgraded to latest BIOS with new Christea. A new version of Christea software will be included in the new EI CD

## Customer Impact of Change and Recommended Action:

This board change is not expected to cause a change to the Microsoft\* Windows\* operating system's software driver stack.

This change are being thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers. NO additional qualification is recommended for this change on platforms received from Intel.

## Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change CA	Pre Change AA	Pre Change PBA	Post Change Product Code	Post Change MM#	Post Change TA	Post Change CA	Post Change AA	Post Change PBA
LAD945PLNML 876654	876654	No change	No change	30652-306	D30503-306	No Change	No Change	No Change	No Change	30652-307	D30503-307

BLKD945PLN ML 878569	87856 9	D3050 0-104	No change	30652 -306	D3050 3-306	No Change	No Change	D3050 0-105	No Change	30652 -307	D3050 3-307
BOXD945PLN ML 878570	87857 0	D3050 1-104	No change	30652 -306	D3050 3-306	No Change	No Change	D3050 1-105	No Change	30652 -307	D3050 3-307
OEMD945PLN ML 883342	88334 2	No change	No change	56261 -302	D5626 2-302	No Change	No Change	No Change	No Change	56261 -303	D5626 2-303

## Reference Documents / Attachments:

**Document:**

**Location #:**

## PCN Revision History:

**Date of Revision:**

**Revision Number:**

**Reason:**

November 2, 2006

00

Originally Published PCN

November 22, 2006

01

Schedule change