



Product Change Notification

109593 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109593 - 00
Change Title: Intel® Compute Module MFS5000SI, Intel® Compute Module MFS5000SI (bulk pack), PCN 109593-00, Product Material, Updating the Firmware Installed in the Factory to V4.1.
Date of Publication: September 23, 2009

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Oct 23, 2009
---	--------------

Description of Change to the Customer:

Updating the firmware installed on the compute module in the factory to V4.1. Update supports upgrade to 2G SD card on the system midplane and brings all platform components to a common firmware level. Reference PCN109490-0x for information on the 2G SD card upgrade.

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers and recommends no additional action.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change Product Code	Post Change MM#	Post Change TA	Post Change PBA
MFS5000SI 900409	900409	D91952-006	D70726-501	MFS5000SI 900409	900409	D91952-007	D70726-502
MFS5000SIB 900410	900410	E19099-004	D70726-501	MFS5000SIB 900410	900410	E19099-005	D70726-502

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision: September 23, 2009	Revision Number: 00	Reason: Originally Published PCN
--	-------------------------------	--