



Product Change Notification

107819 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107819 - 01
Change Title: DG965WH, PCN 107819-01, Product Material, Marvell PATA controller B2 stepping conversion, Reason for Revision: PCN information updated for customer impact. Correct spelling error.
Date of Publication: August 27, 2007

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 10, 2007
---	--------------

Description of Change to the Customer:

Reason for Revision: PCN information updated for customer impact. Correct spelling error.

As part of Intel's continuing commitment to enhance product quality and enhance manufacturability, an updated Marvell PATA controller B2 stepping device will be used.

Customer Impact of Change and Recommended Action:

In Microsoft* Windows* XP*, the pre-existing IDE ATA/ATAPI controller driver will re-enumerate automatically due to the Microsoft* Windows* Plug-and-Play* mechanism. The re-enumeration will impact existing operating system image. User interaction is not required during this process. This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. Intel is not recommending additional qualification of these changes on platforms.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Pre Change PBA	Post Change AA	Post Change PBA
LADG965WHKR	878112	D41693-303	D41689-303	D41693-304	D41689-304
BLKDG965WHMKR	878643	D41692-308	D41688-308	D41692-309	D41688-309
BOXDG965WHMKR	878646	D41692-308	D41688-308	D41692-309	D41688-309

PCN Revision History:

Date of Revision:

August 16, 2007

August 27, 2007

Revision Number:

00

01

Reason:

Originally Published PCN
PCN information updated for
customer impact. Correct spelling
error.