



Product Change Notification

108753 - 04

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108753 - 04
Change Title: S5000PSL, S5000XSL and S5000XVN, PCN 108753-04, Product Design, Update software stack and upgrade to SMS3.0, Reason for Revision: Change BIOS version
Date of Publication: October 13, 2008

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 19, 2008
---	--------------

Description of Change to the Customer:

Reason for Revision: Change BIOS version

Intel is updating the server board software stack (BIOS, BMC, FRUSDR) to BIOS R0085, BMC 64, FRUSDR 46.

Intel is also upgrading the system management software to Intel® System Management Software 3.0 DVD.

Customer Impact of Change and Recommended Action:

Orders for post-change product need to be placed using the new MM#.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
BB5000XVNSATAR 895322	895322	E12391-102	E11030-102	900395	E12391-103	E11030-103
BB5000XVNSASR 895325	895325	E12388-102	E11034-102	900393	E12388-103	E11034-103
BB5000PSLSATAR 895424	895424	E12382-102	E11027-102	900347	E12382-103	E11027-103
BB5000PSLSASR 895426	895426	E12378-102	E11025-102	900346	E12378-103	E11025-103
BB5000PSLROMBR	895428	E12374-002	E11027-102	900407	E12374-003	E11027-103

895428						
BB5000XSLSATAR 895429	895429	E12387-102	E11032-102	900349	E12387-103	E11032-103
S5000PSLR0MBR 891983	891983	E12273-002	E11027-102	891983	E12273-003	E11027-103
S5000PSLSATAR 891984	891984	E12274-002	E11027-102	891984	E12274-003	E11027-103
S5000XVNSASR 891986	891986	E12276-002	E11034-102	891986	E12276-003	E11034-103
S5000XVNSATAR 891999	891999	E12278-002	E11030-102	891999	E12278-003	E11030-103
S5000PSLSASR 892051	892051	E12267-002	E11025-102	892051	E12267-003	E11025-103
SE11025 893694	893694	E20906-102	E11025-102	900390	E20906-103	E11025-103

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

August 21, 2008

00

Originally Published PCN

August 24, 2008

01

Add detail software version

September 10, 2008

02

Add affected products and add
SMS 3.0 change

September 15, 2008

03

Add SE11025 and add PBA
number change

October 13, 2008

04

Change BIOS version