



Product Change Notification

109142 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109142 - 00
Change Title: SR2520SA, PCN 109142-00, Product Design, System (BIK) is being updated with the latest S5000VSA MOBO with BIOS R0095 and includes a new anodized CPU VR heatsink. The Intel(R) System Management Software DVD is also being removed and a new Attention Document is being added.
Date of Publication: January 09, 2009

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 30, 2009
---	--------------

Description of Change to the Customer:

The System (BIK) is being updated with the latest S5000VSA motherboard, with BIOS R0095, and includes a new anodized CPU VR Heatsink.

The Intel(R) Server Management DVD (E18149-002) is being removed from the Software Accessory Kit (SAK P/N change from E54552-002 to E54552-003), and a new Attention document (E58651-001) is being added.

Customer Impact of Change and Recommended Action:

The latest S5000VSA motherboard, with BIOS R0095, includes fixes for the Machine Check Exception (MCE) issue, reported on a relatively small number of S5000VSA baseboards, when using some Intel(R) Xeon(R) 5400 Series Processors.

Standard validation for the above changes is recommended.

Customers needing the Intel® Active System Console, Intel® Management Packs or any of the utilities found on the Intel® System Management Software DVD, can download them from <http://www.intel.com/go/servermanagement>.

Customers, who would like to evaluate Microsoft* System Center Essentials, can download it from <http://www.Microsoft.com/essentials>.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
SR2520SAXSR	892251	E10062-003	E11012-101	900459	E10062-004	E11012-200
SR2520SAXSRNA	893537	E10062-003	E11012-101	900487	E10062-004	E11012-200

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

January 9, 2009

Revision Number:

00

Reason:

Originally Published PCN