



Product Change Notification

106631 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106631 - 00
Change Title: Intel NetStructure® MPCHC0001 14U
Chassis, PCN 106631-00
Changes to: Label, Fan Tray, chassis screws,
and reset switch assembly.
Date of Publication: August 1, 2006


Key Characteristics of the Change:

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sept 1, 2006
---	--------------

Description of Change to the Customer:

1. Changes in certification test requirements the MPCHC0001 is now certified FCC Class A, a change from original FCC Class B certification. This change is reflected on the product safety label.
2. Add alternate fans and additional fan vendors to the Fan Tray. Both existing and new fans may be used in the Fan Tray assembly.
3. The upper card guide support brackets (left and right) are held by 2 screws each, changing the screw length to 12mm from 10mm to allow for better thread engagement.



4. The power reset cables are being replaced with RoHS cables. Current cable will be used until exhausted, and either cable may be found in this Top Assembly.

Customer Impact of Change and Recommended Action:

No customer impact or customer action required

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
MPCHC0001	848998	848998	C94926-011	C94926-012		
MPCHC0001	848998	848998	D13117-006	D13117-007		

Major Subassembly Revision Table

	Pre-Change	Post Change
Chassis TA "US Factory"	C94926-011	C94926-012
Chassis TA "Malaysia Factory"	D36117-006	D36117-007
Sub-Assemblies:		
Fan Tray	C94944-006	C94944-007
Fan PBA	A95800-503	A95800-503
PEM	C94946-005	C94946-005
CDM	D14817-002	D14817-002
14 Slot Filler	C93470-006	C93470-006
Filter Tray - Primary	C94526-008	C94526-008
Alternate	C94526-007	C94526-007
Alternate	C94526-006	C94526-006

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Aug 1, 2006

Revision Number:

00

Reason:

Originally Published PCN