



Product Change Notification

104757 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 104757 - 00
Change Title: SR1400 & SR1400JR2, FYI, Class 2:
Low Profile Riser Card Change
Date of Publication: January 18, 2005

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Product Design

Forecasted Key Milestones:

Customer Must Be Ready To Rev	Feb 07, 2005
--------------------------------------	--------------

Description of Change to the Customer:

A dimensional change is being made to the PCB of the low profile riser card. When inserted into the low profile riser slot on the baseboard, the current riser board PCB has a potential of making contact with a capacitor on the baseboard. The new board will remove PCB material eliminating this risk. No component or schematic changes were made for this PCB change.

The PBA# of the riser card will change from C53356-401 to C53356-501

Customer Impact of Change and Recommended Action:

Intel anticipates no customer impact for this change. Evaluate when available

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
ADWLPRISER	861837	861837	C80218-001	C80218-002	C53356-401	C53356-501
SR1400	857036	857036	C51952-001	C51952-002	C53356-401	C53356-501
SR1400NA	857140	857140	C51952-001	C51952-002	C53356-401	C53356-501
SR1400SYS	865571	865571	C50219-001	C50219-002	C53356-401	C53356-501
SR1400SYSNA	865595	865595	C50219-001	C50219-002	C53356-401	C53356-501

PCN Revision History:

Date of Revision: January 18, 2005	Revision Number: 00	Reason: Originally Published PCN
----------------------------------------------	-------------------------------	--------------------------------------------