



Product Change Notification

107033 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: <mailto:asmo.pcn@intel.com>

Asia Pacific Contact: <mailto:apacgccb@intel.com>

Europe Email: <mailto:eccb@intel.com>

Japan Email: <mailto:jccb.ijkk@intel.com>

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107033 - 00
Change Title: D975XBX2, PCN 107033-00, Product Material, Update BIOS
Date of Publication: November 28, 2006

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Dec 13, 2006
---	--------------

Description of Change to the Customer:

Updating the BIOS to revision 2333

Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition. Detailed BIOS release notes can be viewed from: <http://developer.intel.com/products/motherboard/d975xbx2/tools.htm>

The changes have been thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change AA	Post-Change AA
BLKD975XBX2KR	885036	885036	D53350-504	D53350-505
BOXD975XBX2KR	885040	885040	D53350-504	D53350-505

PCN Revision History:

Date of Revision: November 28, 2006	Revision Number: 00	Reason: Originally Published PCN
---	-------------------------------	--