



Product Change Notification

106509 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106509 - 00
Change Title: Intel® Itanium® 2 Processors (Madison), PCN 106509-00, Product Marking, Marking Change
Date of Publication: July 26, 2006

Key Characteristics of the Change:

Product Marking

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 04, 2006
---	--------------

Description of Change to the Customer:



Addition of the characters "A2" after the sspec on line 2 of the marking on the back of the processor. A2 is an Intel® internal marking related to manufacturing.

OLD:

GRP1 LINE1: PRODUCT NAME
GRP1 LINE2: Sspec XXXXX
GRP1 LINE3: {FPO}-{[SN]}

NEW:

GRP1 LINE1: PRODUCT NAME
GRP1 LINE2: Sspec A2 XXXXX
GRP1 LINE3: {FPO}-{[SN]}



Customer Impact of Change and Recommended Action:

Intel® anticipates no impact to customers.

Products Affected / Intel Ordering Codes:

Tray Intel® Itanium® 2 Processors

Marketing Name	Frequency	Product Code	S-Spec	Material Master #	Stepping
Intel® Itanium® 2 Processors	1.66 GHz 667 FSB 9M	YA80543KF0289M	S L8JJ	872747	A2
Intel® Itanium® 2 Processors	1.66 GHz 667 FSB 6M	YA80543KF0286M	S L8JK	872748	A2
Intel® Itanium® 2 Processors	1.60 GHz 533 FSB 9M	YA80543KE0259M	S L93W	878408	A2
Intel® Itanium® 2 Processors	1.60 GHz 533 FSB 6M	YA80543KE0256M	S L93X	878409	A2
Intel® Itanium® 2 Processors	1.60 GHz 533 FSB 3M	YA80543KE0253M	S L8CZ	869489	A2
Intel® Itanium® 2 Processors	1.60 GHz 400 FSB 9M	YA80543KC0259M	S L8CU	869482	A2
Intel® Itanium® 2 Processors	1.60 GHz 400 FSB 6M	YA80543KC0256M	S L8CV	869484	A2
Intel® Itanium® 2 Processors	1.60 GHz 400 FSB 3M	YA80543KC0253M	S L8CW	869486	A2
Intel® Itanium® 2 Processors	1.50 GHz 400 FSB 4M	YA80543KC0214M	S L8CX	869487	A2
Intel® Itanium® 2 Processors	1.30 GHz 400 FSB 3M	YA80543KC0133M	S L8CY	869488	A2

Boxed Intel® Itanium® 2 Processors

Marketing Name	Frequency	Product Code	S-Spec	MM #	Stepping
Intel® Itanium® 2 Processors	1.60 GHz 400 FSB 9M	BX80543KC1600K	S L8CU	875050	A2
Intel® Itanium® 2 Processors	1.60 GHz 400 FSB 9M	BX80543KC1600KD	S L8CU	874988	A2
Intel® Itanium® 2 Processors	1.60 GHz 400 FSB 6M	BX80543KC1600JD	S L8CV	875046	A2
Intel® Itanium® 2 Processors	1.60 GHz 400 FSB 6M	BX80543KC1600J	S L8CV	875042	A2
Intel® Itanium® 2 Processors	1.60 GHz 400 FSB 3M	BX80543JC1600G	S L8CW	875043	A2
Intel® Itanium® 2 Processors	1.60 GHz 400 FSB 3M	BX80543JC1600GD	S L8CW	875047	A2
Intel® Itanium® 2 Processors	1.50 GHz 400 FSB 4M	BX80543KC1500H	S L8CX	874986	A2
Intel® Itanium® 2 Processors	1.50 GHz 400 FSB 4M	BX80543KC1500HD	S L8CX	875051	A2
Intel® Itanium® 2 Processors	1.30 GHz 400 FSB 3M	BX80543JC1300G	S L8CY	875045	A2
Intel® Itanium® 2 Processors	1.30 GHz 400 FSB 3M	BX80543JC1300GD	S L8CY	875049	A2

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

July 26, 2006

Revision Number:

00

Reason:

Originally Published PCN