



Product Change Notification

106625 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106625 - 01
Change Title: S5000PSL, S5000XSL, S5000XVN, PCN 106625-01, Product Design, Class 1, Change MCH to G1 stepping and software update, Reason for Revision: Updating TA and MM numbers.
Date of Publication: August 18, 2006

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 25, 2006
---	--------------

Description of Change to the Customer:

Reason for Revision: Updating TA and MM numbers.

- Revision change of the Intel 82006MCH from the B2 stepping to the G1 stepping.
- Replacement of VRM heat sink to enable alternate manufacturer.
- Software update to BIOS 59, FRUSDR 33a.

Customer Impact of Change and Recommended Action:

Intel recommends that customers do a basic level of validation. Customers ordering OEM 10-pack will need to use new MM#.

Products Affected / Intel Ordering Codes:

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BB5000PSLROMB	885906	886320	D49144-801	D49144-803	D44771-801	D44771-803
BB5000PSLSAS	885905	886315	D49143-801	D49143-803	D44749-801	D44749-803
BB5000PSLSATA	885904	886314	D49142-801	D49142-803	D44771-801	D44771-803
BB5000XSL SATA	885907	886319	D49145-801	D49145-803	D16310-801	D16310-803
BB5000XVNSAS	881241	886322	D49141-801	D49141-803	D25028-801	D25028-803
BB5000XVNSATA	881242	886321	D49140-801	D49140-803	D37261-801	D37261-803
S5000PSLROMB	881238	886037	D50358-002	D50358-004	D44771-801	D44771-803
S5000PSLSAS	881235	886036	D50359-002	D50359-004	D44749-801	D44749-803
S5000PSLSATA	881732	886032	D50360-003	D50360-005	D44771-801	D44771-803
S5000XVNSAS	881240	886042	D50361-001	D50361-003	D25028-801	D25028-803
S5000XVNSATA	881234	886040	D50362-001	D50362-003	D37261-801	D37261-803

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
August 4, 2006	00	Originally Published PCN
August 18, 2006	01	Updating TA and MM numbers.