



Product Change Notification

108578 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108578 - 00
Change Title: Intel® SL1461, SL2101, SP5055, and SP5655 Tuners, PCN 108578-00, Product Discontinuance
Date of Publication: June 25, 2008

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Product Discontinuance Program Support Begins:	Jun 25, 2008
Orders for Discontinued Products Become Non-Cancelable:	Dec 26, 2008
Last Product Discontinuance Order Date:	Dec 26, 2008
Last Product Discontinuance Shipment Date:	Jun 25, 2009

Description of Change to the Customer:

Due to a shift in demand, the Intel® SL1461, SL2101, SP5055, and SP5655 Tuners will be discontinued and unavailable for additional orders after the "Last Product Discontinuance Order Date" (see "Forecasted Key Milestones" above).

Please refer to the "Products Affected" table below for the SL1461, SL2101, SP5055, and SP5655 line items included in this notification.

Customer Impact of Change and Recommended Action:

Please determine your remaining demand for the these products and place your "Last Product Discontinuance Orders" in accordance with the "Forecasted Key Milestones" listed above.

Products Affected / Intel Ordering Codes:

Product Code	S-Spec	MM#
EPSSL2101	S L9FF	882502
EPSSL2101		882503
QHSL1461	S L9FL	882538
QHSL1461		882539
QHSP5055		882540
QHSP5055	S L9FM	882541
QHSP5655	S L9FN	882542
QHSP5655		882543

Reference Documents / Attachments:**Document:****Location #:****PCN Revision History:****Date of Revision:****Revision Number:****Reason:**

June 25, 2008

00

Originally Published PCN