



# Product Change Notification

## 107994 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 107994 - 01  
**Change Title:** SR4850HW4M,SHW4URM3SA,SR6850HW4M and SHW6URM3SA, PCN 107994-01, Product Design, Class2: Accessories FHWSATAIDE: Stepping change for Controller chip on SATA bridge board, Reason for Revision: TA update  
**Date of Publication:** February 17, 2008

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Feb 21, 2008
---	--------------

## Description of Change to the Customer:

### Reason for Revision: TA update

Current A4 stepping of Marvell controller chip on SATA bridge board is going EOL and chang to B1 stepping.

SR4850HW4M (SHW4URM)

MM# 879454

Change top assembly part number from D35286-009 to D35286-010

Change the SATA bridge board part number from C71688-003 to C71688-004

SHW4URM3SA

MM# 886995

Change top assembly part number from D46299-007 to D46299-008

Change the SATA bridge board part number from C71688-003 to C71688-004

SR6850HW4M (SHW6URM)

MM#879452

Change top assembly part number from D35289-008 to D35289-009

Change the SATA bridge board part number from C71688-003 to C71688-004

SHW6URM3SA

MM# 887385

Change top assembly part number from D46296-008 to D46296-009

Change the SATA bridge board part number from C71688-003 to C71688-004

FHWSATAIDE

MM# 870273

Change the top assemble number from D10881-003 to D10881-004

Change the board part number from C71688-003 to C71688-004

### Customer Impact of Change and Recommended Action:

No significant impact on product/process/material performance, appearance, quality, reliability, interchangeability, functionality or customer handling and manufacturability.

### Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
SHW6URM	879452	D35289-008	N/A	D35289-009	N/A
SHW4URM	879454	D35286-009	N/A	D35286-010	N/A
FHWSATAIDE	870273	D10881-003	C71688-003	D10881-004	C71688-004
SHW4URM3SA	886995	D46299-007	N/A	D46299-008	N/A
SHW6URM3SA	887385	D46296-008	N/A	D46296-009	N/A

### Reference Documents / Attachments:

Document:

Location #:

### PCN Revision History:

Date of Revision:

Revision Number:

Reason:

October 11, 2007

00

Originally Published PCN

February 17, 2008

01

TA update