



Product Change Notification

108781 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108781 - 01
Change Title: Intel(R) IP Network Server NSC2U, PCN 108781-01, Product Material, Cable shield removal, Reason for Revision: Canceling this change
Date of Publication: February 18, 2009

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 28, 2008
---	--------------


Description of Change to the Customer:

Reason for Revision: Canceling this change

This change is canceled because there is no technical requirement to remove the cable shield. This reduces the number of changes to the product. Customers should continue to integrate and use the product as normal.


Original PCN message follows:

Intel has removed the cable shield that protected the baseboard power cables. The shield was located under the 40 mm fan set.



Old design with shield to protect the baseboard power cables.

Revised design without shield.



Original design required the shield because the metal fan shroud was in contact with the cables.



Plastic fan shroud design provides more relief for power cables. Revised system design has shield removed.

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers. Since modifying the 40 mm fan shroud design (PCN#108474) the cable shield is no longer functional.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change TA	Post Change TA
NSCD0202W 900074	900074	NA	NA
NSCA0202W 900075	900075	NA	NA

PCN Revision History:

Date of Revision:

August 29, 2008

February 18, 2009

Revision Number:

00

01

Reason:

Originally Published PCN

Canceling this change