



# Product Change Notification

**Change Notification #:** 119444-01

**Change Title:** Select Trusted Platform Module 2.0  
AAXXTPMENC9  
PCN 119444-01, Product Design,  
New TPM for M50CYP Server Family  
**Reason for Revision: Updated change title to "New  
TPM IC and Firmware Update"**

**Date of Publication:** February 21, 2023

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material*</b>	February 23, 2023
---	-------------------

\* Intel appreciates the customer's desire to receive the latest revision of products. However, Intel manages inventory on a first in first out (FIFO) basis at the MM# level. Subsequently, customer requests for a specific revision of material (below the MM#) will not be supported by Intel.

## Description of Change to the Customer:

### **Reason for Revision: Updated change title to "New TPM IC and Firmware Update"**

Intel is implementing the following change on the item listed in the "Products Affected" table.

Intel is upgrading the Trusted Platform Module (TPM) IC from version SLB9670 to SLB9672, updating its firmware version from 7.85 to 15.21.

Starting March 31st, Windows 2024 customers will need TPM SLB9672 in order to provision and certify their server systems. Previous TPM SLB9670 is still compatible with earlier Windows versions.

## Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers.

Please contact your local Intel Field Sales Representative if you have any further questions about these changes.

### Products Affected/Intel Ordering Codes:

Marketing Name	Product Code	MM#	Pre Change TA	Pre Change PBA	Post Change MM	Post Change TA	Post Change PBA
Trusted Platform Module 2.0 AAXXTPMENC9, Single	AXXTPMENC9	99C69H	M92102-001	M91855-150	99C8ZW	N10620-001	N10413-150

### PCN Revision History:

**Date of Revision:**

February 08, 2023

February 21, 2023

**Revision Number:**

00

01

**Reason:**

Originally Published PCN

Updated change title to "New TPM IC and Firmware Update"



# Product Change Notification

## 119444-01

### Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at [www.intc.com](http://www.intc.com).

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)