



# Product Change Notification

## 105568 - 06

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 105568 - 06  
**Change Title:** SR6850HW4 and SR4850HW4,  
PCN 105568-06, Product Material,  
**CLASS 1: BIOS Update and chassis parts  
changes to RoHS compliant,  
Reason for Revision: Add chassis parts  
change to RoHS**  
**Date of Publication:** March 01, 2006

## Key Characteristics of the Change:

Product Material

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Mar 03, 2006
---	--------------

## Description of Change to the Customer:

### Reason for Revision: Add chassis parts change to RoHS

#### SHW4UR

- Change the MM# from 874581 to 877483
- Change top assembly part number from C92307-008 to C92307-009
- Change the BIOS to P06
- Change chassis parts to RoHS compliant
  - Change chassis option part number from C55971-007 to C55971-008
  - Change chassis assembly from C54427-008 to C54427-009
  - Change chassis base from C82411-005 to C82411-006
  - Change PCI bulkhead from D11997-001 to D11997-002
  - Change CD carrier from C58601-005 to C58601-006
  - Change 5.25 filler from C58576-005 to C58576-006
  - Change top cover from C82415-002 to C82415-003

#### SHW6UR

- Change the MM# from 874583 to 877485
- Change top assembly part number from C92308-008 to C92308-009
- Change the BIOS to P06
- Change chassis parts to RoHS compliant
  - Change chassis option part number from C69685-005 to C69685-006
  - Change chassis assembly from C69408-005 to C69408-006
  - Change chassis base from C54778-007 to C54778-008
  - Change top cover from C90667-001 to C90667-002
  - Change PCI bulkhead D11997-001 to D11997-002
  - Change CD carrier from C58601-005 to C58601-006
  - Change 5.25 filler from C91863-003 to C91863-004

BIOS P06:

BIOS update supports Intel® Xeon® Processor 7000 sequence

Chassis:

Chassis parts are changing to Restriction of Hazardous Substances (RoHS) compliant.

### Customer Impact of Change and Recommended Action:

No significant impact on product/process/material performance, appearance, quality, reliability, interchangeability, functionality or customer handling and manufacturability.

### Products Affected / Intel Ordering Codes:

#### System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SHW4UR	874581	877483	C92307-008	C92307-009	C54427-008	C54427-009
SHW6UR	874583	877485	C92308-008	C92308-009	C69408-005	C69408-006

### Reference Documents / Attachments:

Document:

Location #:

### PCN Revision History:

Date of Revision:	Revision Number:	Reason:
October 7, 2005	00	Originally Published PCN
November 1, 2005	01	Implementation date change.
November 11, 2005	02	Change BIOS release to P06. Add BHWBASE to PCN. Change the implementation date.
December 21, 2005	03	Add top assembly part numbers. PDL change. Change to Fibre Channel Module slot. Change implementation date.
January 10, 2006	04	New date for implementation. Remove top assembly part number for the SHW6UR.
February 13, 2006	05	Remove fibre channel slot change. Remove PLD update. Remove main board part number change. Change the implementation date. Remove BHWBASE from PCN.
March 1, 2006	06	Add chassis parts change to RoHS.