



Product Change Notification

106426 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106426 - 00
Change Title: D945GCZ, PCN 106426-00, Product Design, BIOS update to incorporate new SPI parts
Date of Publication: June 14, 2006

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jun 30, 2006
---	--------------

Description of Change to the Customer:

1. Update the system BIOS to NT94510J.86A.3814.2006.0414.1513 to support new SPI parts:
 - a. SST SST25VF080B
 - b. Atmel AT26DF081
 - c. ST Micro M25PE80-VMW6G

Please go to <http://www.intel.com/products/motherboard/d945gcz/> for the BIOS release notes.

Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. UPSD is not recommending additional qualification of these changes on platforms received from Intel. These board changes are not expected to cause a change to the Microsoft* Windows* operating system's software driver stack. No expected OS image change.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change AA	Post-Change AA	Pre-Change PBA	Post-Change PBA
BLKD945GCZLKR	869570	869570	C99567-504	C99567-505	C99568-504	C99568-505
BOXD945GCZLKR	869569	869569	C99567-504	C99567-505	C99568-504	C99568-505
LAD945GCZLKR	868924	868924	C99567-504	C99567-505	C99568-504	C99568-505

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
June 14, 2006	00	Originally Published PCN