



Product Change Notification

103626 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2003. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash, Trillium is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 103626 - 00
Change Title: SR2300/SR1300, PCN 103626-00, FYI, Class 2; CD/Floppy Assembly Firmware Update
Date of Publication: October 01, 2003

Type of Change Notification:

FYI - (For Your Information)

Key Characteristics of the Change:

Software

Forecasted Key Milestones:

Date of First Availability of Post-Conversion Material:	Oct 17, 2003
--	--------------

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

CDROM firmware will be changing from N 101 to N 102

Customer Impact of Change and Recommended Action:

CDROM firmware will be changing from N 101 to N 102 - Customer needs to be aware of the change; no impact to customer expected.

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SE7501WV2SKU02	855630	855630	C22264-010	C22264-011	A57464-003	A57464-004
SWV1USKU07	853491	853491	C32003-005	C32003-006	A57464-003	A57464-004
SWV2USKU07	853492	853492	C32002-005	C32002-006	A57464-003	A57464-004

Component Product Table

Pre-Conversion Product Code	Pre-Conversion Spec/ROM	Pre-Conversion MM#	Post-Conversion Product Code	Post-Conversion Spec/ROM	Post-Conversion MM#
AXXCDFLOPPY	A57464-003	836911	AXXCDFLOPPY	A57464-004	836911

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

October 1, 2003

00

Originally Published PCN