



# Product Change Notification

## 106912 - 03

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 106912 - 03  
**Change Title:** SR6850HW4M and SHW6URM3SA, PCN 106912-03, Product Design, Class 2: AHW6UPWR-Power supply change to improve RFI margin, Reason for Revision: Correct TA number  
**Date of Publication:** November 04, 2007

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Nov 09, 2007
---	--------------

## Description of Change to the Customer:

### Reason for Revision: Correct TA number

Replace current AC socket and adjust component values in EMI stage to improve RFI margin.

SR6850HW4M (SHW6URM)

MM# 879452

Change top assembly part number from D35289-007 to D35289-008

Change power supply part number from D37230-001 to D37230-002

SHW6URM3SA

MM# 887385

Change top assembly part number from D46296-007 to D46296-008

Change power supply part number from D37230-001 to D37230-002

AHW6UPWR

MM# 881376

Change top assembly part number from C76592-004 to C76592-005

Change power supply part number from D37230-001 to D37230-002

## Customer Impact of Change and Recommended Action:

No significant impact on product/process/material performance, appearance, quality, reliability, interchangeability, functionality or customer handling and manufacturability.

## Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
AHW6UPWR 881376	881376	C76592-004	D37230-001	C76592-005	D37230-002
SHW6URM 879452	879452	D35289-007	N/A	D35289-008	N/A
SHW6URM3SA 887385	887385	D46296-007	N/A	D46296-008	N/A

## Reference Documents / Attachments:

Document:

Location #:

## PCN Revision History:

Date of Revision:

Revision Number:

Reason:

November 3, 2006

00

Originally Published PCN

July 30, 2007

01

Roadmap Change, MM#,TA  
number update

November 1, 2007

02

TA number update

November 4, 2007

03

Correct TA number