



Product Change Notification

104039 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geography location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: <mailto:asmo.pcn@intel.com>

Asia Pacific Contact: <mailto:apacgccb@intel.com>

Europe Email: <mailto:eccb@intel.com>

Japan Email: <mailto:jccb.ijkk@intel.com>

Copyright © Intel Corporation 2004. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANdesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash, Trillium is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 104039 - 00
Change Title: MPCMM0001, PCN 104039-00, FFF, CLASS 2 : FLASH, EJECTOR, INSULATOR, SHIPPING LABEL SPEC CHANGE
Date of Publication: April 14, 2004

Type of Change Notification:
FFF - (Form-Fit-Function)

Key Characteristics of the Change:

Product Material
Product Design
Documentation

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 09, 2004
---	--------------

Description of Change to the Customer:

1. REMOVE FLASH A04122-007 AS ALTERNATE COMPONENT
2. REPLACE EJECTOR HANDLE C21037-004 WITH C68059-001
3. ADD NEW INSULATOR C68871-001 UNDER EJECTOR HANDLE
4. REPLACE LABEL SPEC C55882 WITH C67334

Customer Impact of Change and Recommended Action:

1. REMOVE FLASH A04122-007 AS ALTERNATE COMPONENT
Removed alternate p/n from Bill-of-Material that had not been qualified. There were no factory escapes.
2. REPLACE EJECTOR HANDLE C21037-004 WITH C68059-001
The ejector latch on some early boards may not hold the ejector tightly, which may cause the CMM not to boot properly or may cause a running CMM deactivate as though it is being extracted. Please contact your Intel representative for instructions on CMM replacement.
3. ADD NEW INSULATOR C68871-001 UNDER EJECTOR HANDLE
Added insulator below ejector handle to prevent ejector handle from rubbing on PCB. If customer CMM has a Top Assembly (TA) number of C52711-009 or lower, please contact your Intel representative.
4. REPLACE LABEL SPEC C55882 WITH C67334
Updated package label spec.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
MPCHC0001 848998	848998					
MPCMM0001	850830		C52711-009	C52711-010	A97016-503	A97016-504

Reference Documents / Attachments:

Document:	Location #:
MPCMM0001 Home page	http://www.intel.com/design/network/products/cbp/atca/mpcmm0001.htm
MPCMM0001 Technical Docs (TPS, Update, etc)	http://www.intel.com/design/network/products/cbp/docs/mpcmm0001.htm

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
April 14, 2004	00	Originally Published PCN